



General information

Make	MINI
Model	COOPER AUTO COOPER
Colour	Blue
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-17
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-28
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	13
Total items failed	3

MOT #13	2023-03-25 17:43
MOT test number	349466084336
Result	✓ Passed
Next expiry date	2024-03-28

MOT #12	2022-03-29 08:17
MOT test number	329472952577
Result	✓ Passed

MOT #11	2021-12-16 13:12
MOT test number	647344871835
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2020-12-22 14:58
MOT test number	183481480650
Result	✓ Passed

Advice Nearside Rear Valve stem slightly damaged ADVISE REPLACEMENT, DUE TO SPLITTING (5.2.3 (j))

Advice Offside Rear Tyre slightly damaged/cracking or perishing CRACKING - SPLITTING ON TREAD (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing CRACKING - SPLITTING ON TREAD - 195/55/16 (5.2.3 (d) (ii))

**MOT #9** 2019-10-23 09:11**MOT test number** 626702151264**Result** ✓ Passed**MOT #8** 2018-10-09 08:50**MOT test number** 719089368681**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing 195/55/16 (5.2.3 (d) (ii))**Advice** Nearside Front Tyre valve perished.**Advice** Nearside Rear Tyre valve perished.**Advice** Offside Front Tyre slightly damaged/cracking or perishing 195/55/16 (5.2.3 (d) (ii))**Advice** Undertrays fitted, restricting inspection.**Advice** Offside Front Tyre valve perished.**MOT #7** 2017-10-09 10:41**MOT test number** 940102638874**Result** ✓ Passed**MOT #6** 2016-10-07 09:05**MOT test number** 779259920783**Result** ✓ Passed**MOT #5** 2015-10-15 08:44**MOT test number** 101555801237**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit starting to wear outer edge (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit starting to wear outer edge (4.1.E.1)

**MOT #4** 2014-10-22 14:09**MOT test number** 355355494438**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-09-30 11:25**MOT test number** 197573773249**Result** ✓ Passed**MOT #2** 2012-10-01 17:04**MOT test number** 936965572280**Result** ✓ Passed**MOT #1** 2012-10-01 17:04**MOT test number** 866905772288**Result** ✗ Failed

- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2024

X

MOT

Expired:
28 March 2024

Tax status	Expired at 31 January 2024
Days left	88 days too late
MOT expiry date	28 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-10-22
Last registration	2023-03-25
Complete history	See info



Registration #1	2009-10-22	19 mi
Registration #2	2012-10-01	10.488 mi
Registration #3	2013-09-30	11.776 mi
Registration #4	2014-10-22	13.603 mi
Registration #5	2015-10-15	14.641 mi
Registration #6	2016-10-07	16.179 mi
Registration #7	2017-10-09	18.386 mi
Registration #8	2018-10-01	20.593 mi
Registration #9	2019-10-01	22.800 mi
Registration #10	2020-10-01	25.007 mi
Registration #11	2021-10-01	27.214 mi
Registration #12	2022-10-01	29.421 mi
Registration #13	2023-03-25	31.628 mi
Registration #14	2023-03-25	33.835 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1378 mm
Length	3728 mm
Wheel base	2467 mm
Kerb weight	1135 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	B2111316
---------------	----------