



X6WCH

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | BMW |
| Model | X6 XDRIVE35D |
| Colour | Grey |
| Year of manufacture | 2009 |
| Top speed | 147 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 282 BHP |
| Max. torque | 580 Nm at 1.750 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 39.8 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 220 g/km |
| CO2 label | K |








Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-09 |
| Pictures | 13 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-10 |
| MOT pass rate | 70 % |
| MOT passed | 14 |
| Failed MOT tests | 6 |
| Total advice items | 25 |
| Total items failed | 8 |

| | |
|------------------|--|
| MOT #20 | 2023-06-23 07:05 |
| MOT test number | 744278974482 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-10 |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

| | |
|------------------|---|
| MOT #19 | 2023-06-19 12:51 |
| MOT test number | 803504015026 |
| Result | ✗ Failed |
| MAJOR | Exhaust particulate filter missing where one was fitted as standard (8.2.2.1 (a)) |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) |
| DANGEROUS | Nearside Rear Road wheel fractured two cracks on the inner rim (5.2.2 (a)) |

| | |
|-----------------|------------------|
| MOT #18 | 2022-07-11 12:26 |
| MOT test number | 599949411548 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #17 | 2021-06-21 10:20 |
| MOT test number | 415746686397 |
| Result | ✓ Passed |

**MOT #16**

2020-06-23 08:23

MOT test number

466732073534

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))**MOT #15**

2019-07-11 14:19

MOT test number

694795348300

Result

✓ Passed

Advice Offside Front Lower Suspension arm ball joint has slight play lift play (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play lift play (5.3.4 (a) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front arm front bush both sides (5.3.4 (a) (i))**MOT #14**

2019-07-10 12:52

MOT test number

946947485761

Result

✗ Failed

MAJOR Nearside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake pad wear indicator warning light is on**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement front arm front bush both sides (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play lift play (5.3.4 (a) (i))**MAJOR** Front Headlamp cleaning device for LED or HID headlamp inoperative both sides (4.1.6 (a) (ii))**MAJOR** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play lift play (5.3.4 (a) (i))

**MOT #13** 2018-05-31 14:37**MOT test number** 206192113812**Result** ✓ Passed**MOT #12** 2018-05-31 14:37**MOT test number** 431092085615**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11** 2017-05-31 14:42**MOT test number** 152868070823**Result** ✓ Passed**MOT #10** 2016-06-14 11:26**MOT test number** 592089763519**Result** ✓ Passed**MOT #9** 2016-04-14 09:12**MOT test number** 308772785045**Result** ✓ Passed**Advice** Offside Rear tyre worn on inner edge**MOT #8** 2015-04-29 12:44**MOT test number** 477419715139**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #7** 2015-04-29 10:08**MOT test number** 239669815461**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Registration plate character(s) laid out in an incorrect format (6.3.4f)**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2014-04-30 14:58**MOT test number** 196890824151**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2014-02-05 16:33**MOT test number** 185436934005**Result** ✓ Passed**MOT #4** 2013-11-14 11:03**MOT test number** 935218613327**Result** ✓ Passed**MOT #3** 2013-11-14 10:35**MOT test number** 996658713307**Result** ✗ Failed**Fail** Offside Front Headlamp cleaning device inoperative (1.7.2)**Fail** Nearside Front Headlamp cleaning device inoperative (1.7.2)



| | |
|-----------------|------------------|
| MOT #2 | 2012-11-19 13:20 |
| MOT test number | 526764022307 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2012-11-19 10:27 |
| MOT test number | 468284822453 |
| Result | ✗ Failed |

- Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
10 July 2024

| | |
|------------------|---------------------------------|
| Tax status | Expired at 1 March 2024 |
| Days left | 59 days too late |
| MOT expiry date | 10 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2009-11-27 |
| Last registration | 2023-06-23 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-11-27 | 18 mi |
| Registration #2 | 2012-11-19 | 44.549 mi |
| Registration #3 | 2012-11-19 | 44.549 mi |
| Registration #4 | 2013-11-14 | 59.413 mi |
| Registration #5 | 2013-11-14 | 59.413 mi |
| Registration #6 | 2014-02-05 | 61.131 mi |
| Registration #7 | 2014-04-30 | 61.412 mi |
| Registration #8 | 2015-04-29 | 65.506 mi |
| Registration #9 | 2015-04-29 | 65.507 mi |
| Registration #10 | 2016-04-14 | 73.438 mi |
| Registration #11 | 2016-06-14 | 74.806 mi |
| Registration #12 | 2019-06-20 | 75.277 mi |
| Registration #13 | 2019-06-20 | 75.277 mi |
| Registration #14 | 2019-06-20 | 75.277 mi |
| Registration #15 | 2019-06-20 | 75.277 mi |
| Registration #16 | 2019-06-20 | 75.277 mi |
| Registration #17 | 2019-06-20 | 75.277 mi |
| Registration #18 | 2019-06-20 | 75.277 mi |
| Registration #19 | 2019-06-20 | 75.277 mi |
| Registration #20 | 2019-06-20 | 75.277 mi |
| Registration #21 | 2019-06-20 | 75.277 mi |
| Registration #22 | 2019-06-20 | 75.277 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1983 mm |
| Height | 1690 mm |
| Length | 4877 mm |
| Wheel base | 2933 mm |
| Kerb weight | 2110 kg |
| Max. allowed weight | 2710 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 85 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 4 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 23237204 |