





### General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







# Internet history

Entry 1

Date Pictures 2022-02-10

18

Listing price

View report



source: autotrader.co.uk



### MOT history

MOT expiry date	2025-03-11
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	18
Total items failed	8

MOT #19	2024-03-04 12:39
MOT test number	234531590118
Result	✓ Passed
Next expiry date	2025-03-11

MOT #18	2023-03-09 17:59
MOT test number	540169215696
Result	🗸 Passed
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	

MOT #17		2022-03-09 14:23
MOT test	number	555206583548
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #16	2021-03-05 14:00
MOT test number	287423998596
Result	✓ Passed





MOT #15	2020-03-12 16:34	
MOT test number	183217316963	
Result	✓ Passed	
MOT #14	2020-03-11 16:00	
MOT test number	484204137593	
Result	🗙 Failed	
<b>Fail</b> Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
MOT #13	2019-04-05 08:40	
MOT test number	162849671675	
Result	✓ Passed	
MOT #12	2018-04-13 09:17	
MOT test number	507446643766	
Result	✓ Passed	
Advice Offside Front Tyre worn close to the legal limit 3/4 wear (4.1.E.1)		
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but movement rear bush (2.4.G.2)	t not resulting in excessive	

MOT #11	2017-04-24 09:47
MOT test number	905492795851
Result	✓ Passed
MOT #10	2016-03-26 08:25

MOT test number	277390556437
Result	✓ Passed





MOT #9	2016-03-24 11:33
MOT test number	448084900676
Result	🗙 Failed
Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)	
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Rear tyres perrished 185/60/14 82H	

MOT #8	2015-03-20 15:04
MOT test number	259359775079
Result	✓ Passed
<b>Notice</b> Both rear tyres perished on sidewall	

МОТ #7	2015-03-18 14:02
MOT test number	758597675054
Result	🗙 Failed
Notice Both rear tyres perished on sidewall	
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excession	ve movement (2.4.G.2)
Fail Offside Front coil spring broken (2.4.C.1a)	
Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive	e movement (2.4.G.2)

MOT #6		2014-03-18 14:07
MOT test	number	878387774043
Result		✓ Passed
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in	excessive movement
Notice	Both rear tyres perished badly on outer side walls.	
<b>Advice</b> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in e	xcessive movement





MOT #5		2014-03-18 14:07
MOT test number		705397974052
Result		🗙 Failed
Advice Nearside Front S (2.4.G.2)	Suspension arm rubber bush deteriorated	but not resulting in excessive movement
Pass with rectification	Offside Front Headlamp not working on	dipped beam (1.7.5a)
Advice Offside Front Su (2.4.G.2)	spension arm rubber bush deteriorated bu	ut not resulting in excessive movement
<b>Notice</b> Both rear tyres	perished badly on outer side walls.	

MOT #4		2013-03-21 13:44
MOT test	number	106450283094
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Rear seat belts not acsesable	
L		

MOT #3	2012-02-24 14:36
MOT test number	289555252058
Result	✓ Passed

MOT #2	2012-02-23 09:27
MOT test number	419244152088
Result	🗙 Failed

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

MOT #1	2011-03-21 15:51
MOT test number	448090481066
Result	✓ Passed
Notice Rear washer not working	



Tax & MOT check

	√ Faxed		✓ MOT
<b>Tax due:</b> 1 May 2025		Expires: 11 March 2025	
Tax status			Valid until 1 May
Days left			367
MOT expiry date			11 March 2025
Full MOT history			<u>See MOT history</u>

## Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CHE D
Date	*
Category	ame
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
********	
and a second sec	
***********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 



LD08SEY report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-26
Last registration	2024-03-04
Complete history	See info



Registration #1	2008-03-26	19 mi
Registration #2	2011-03-21	12.877 mi
Registration #3	2012-02-23	18.613 mi
Registration #4	2012-02-24	18.613 mi
Registration #5	2013-03-21	25.637 mi
Registration #6	2014-03-18	35.034 mi
Registration #7	2015-03-18	38.320 mi
Registration #8	2015-03-20	38.320 mi
Registration #9	2016-03-24	13.160 mi
Registration #10	2016-03-26	13.160 mi
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		01.777 est
Registration #19		10.207 mi
Registration #20		01.777 est







### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

**NCAP** rating

Video

see crash video

\*\*\*\*



#### Dimensions & weight Width 1660 mm Height 1544 mm Length 3828 mm Wheel base 2465 mm Kerb weight 1069 kg Max. allowed weight 1480 kg Additional information Fuel tank capacity 50 I **Fuel delivery Multi-Point Injection** Number of doors 3

CarCheck.co.uk

Number of seats	4
Number of axles	2
Engine number	BMD 378141