





General information

Make	HYUNDAI
Model	SANTA FE V6
Colour	Black
Year of manufacture	2006
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	250 Nm at 4.000 rpm
Engine capacity	2.656 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	30.1 mpg
Consumption combined	24.8 mpg
CO2 emission	274 g/km
CO2 label	М





MOT history

MOT expiry date	2021-03-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	10

MOT #16	2020-03-18 16:55
MOT test number	614666645927
Result	✓ Passed
Next expiry date 2021-03-1	
Advice Power steering component has slight seepage from a component steering rack (2.1.5 (a))	

MOT #15	2020-03-18 15:08
MOT test number	839380928291
Result	🗙 Failed
Advice Power steering component has slight seepage from a component steering rack (2.1.5 (a)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the	
ingress of dirt (6.1.7 (g) (ii))	



EAO6MLX report date: 2024-03-28

MOT #14	2019-04-04 13:39
MOT test number	315514883697
Result	✓ Passed
Advice Nearside Front Valve stem slightly damaged (5.2.3 (j))	
Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Offside Front Valve stem slightly damaged (5.2.3 (j))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2019-04-04 13:39	
MOT test number	999383301113	
Result	🗙 Failed	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))		
Advice Nearside Front Valve stem slightly damaged (5.2.3 (j))		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Valve stem slightly damaged (5.2.3 (j))		
Minor Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1	1.7 (g) (i))	

MOT #12	2018-03-26 12:13
MOT test number	247325026962
Result	✓ Passed



MOT #11	2018-03-22 12:37
MOT test number	594243553390
Result	🗙 Failed
Fail Nearside Rear Stop lamp not working (1.2.1b)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)	
Fail Front front brake excessively fluctuating (3.7.B.3)	
MOT #10	2017-03-29 11:50
MOT test number	493951088472
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #9	2016-04-18 08:16
MOT test number	487374578980
Result	✓ Passed



Engine covers and under trays fitted





MOT #8	2016-04-14 07:43
MOT test number	146725232499
Result	🗙 Failed
Fail Offside Rear Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Engine covers and under trays fitted	
Fail Nearside Rear Stop lamp not working (1.2.1b)	
Fail Offside Rear Stop lamp not working (1.2.1b)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Centre Rear Stop lamp not working (1.2.1b)	

MOT #7	2015-04-16 12:09
MOT test number	657526205194
Result	✓ Passed
MOT #6	2014-04-08 09:54
MOT test number	958718394079
Result	✓ Passed
MOT #5	2013-04-20 08:37
MOT test number	257020113115
Result	✓ Passed
MOT #4	2012-04-10 10:40
MOT test number	927491402112

EA06MLX

report date: 2024-03-28

Result

🗸 Passed





MOT #3	2011-04-05 10:44
MOT test number	276565391066
Result	✓ Passed
MOT #2	2010-03-29 10:53
MOT test number	371848380020
Result	✓ Passed
MOT #1	2009-03-28 09:49
MOT test number	903137389003
Result	✓ Passed



EAO6MLX report date: 2024-03-28

Tax & MOT check

X Untaxed Tax expired: 16 February 2021	X MOT Expired: 17 March 2021
Tax status	Expired at 16 February 2021
Days left	1168 days too late
MOT expiry date	17 March 2021
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	1000-20-20
Current registration	
Plate since	

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-31
Last registration	2020-03-18
Complete history	See info



Registration #1	2006-03-31	22 mi
Registration #2	2009-03-28	12.929 mi
Registration #3	2010-03-29	18.335 mi
Registration #4	2011-04-05	22.557 mi
Registration #5	2012-04-10	28.126 mi
Registration #6	2013-04-20	39.492 mi
Registration #7	2014-04-08	46.036 mi
Registration #8	2015-04-16	51.243 mi
Registration #9	2016-04-14	56.807 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 est
Registration #13		11.117 esi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1820 mm
Height	1730 mm
Length	4500 mm
Wheel base	2620 mm
Kerb weight	1681 kg
Max. allowed weight	2380 kg
Additional information	
Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	46BA5402159