





report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

## Entry 1

Date	2021-08-28
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

**MOT** history

MOT expiry date	2023-08-11
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	12
Total items failed	11

MOT #18	2022-08-09 10:49
MOT test number	157418307233
Result	<b>✓</b> Passed
Next expiry date	2023-08-11
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2021-08-12 15:30
MOT test number	251705582067
Result	<b>✓</b> Passed

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #16** 2021-08-05 09:58 **MOT** test number 187266206026 Result × Failed Fail Offside Front Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii)) Offside Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Nearside Rear Emissions not tested revs wont hold (8.2.1.2 (d)) Fail Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i)) Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #15

MOT test number

686419428561

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2020-07-21 09:50

MOT test number

651360445925

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

 MOT #13
 2019-07-08 08:49

 MOT test number
 707727684196

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



Result

MM07PKE

report date: 2024-03-29

× Failed

**MOT #12** 2019-06-28 08:12

**MOT test number** 764089921202

**Result** X Failed

Fail Offside Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

Fail Nearside Rear Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #11** 2018-07-03 08:06

MOT test number 851066353384

**Result** ✓ Passed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2018-07-03 08:05

**MOT test number** 106364084875

Result × Failed

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Offside Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #9 2017-07-05 12:26

MOT test number 316046208525

**Result** 
✓ Passed

**MOT #8** 2017-07-05 12:26

**MOT test number** 603569551154

**Pass with rectification** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7	2016-07-01 11:09
MOT test number	976763674881
Result	<b>✓</b> Passed
MOT #6	2015-06-29 11:53
MOT test number	565680885177
Result	✓ Passed
MOT #5	2014-07-02 10:28
MOT test number	849593484176
Result	✓ Passed
MOT #4	2013-07-03 12:03
MOT test number	246834583498
Result	✓ Passed
MOT #3	2012-07-04 13:01
MOT test number	139776882126
Result	✓ Passed
MOT #2	2011-07-04 11:38
MOT test number	978165481102
Result	✓ Passed
MOT #1	2010-07-05 11:17
MOT test number	660566780154
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax expired: 29 November 2022

# X MOT

Expired: 11 August 2023

Tax status	Expired at 29 November 2022
Days left	517 days too late
MOT expiry date	11 August 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category
Type

Damage 2

Category

Date

Туре



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	BB-0-0
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-07-05
Last registration	2022-08-09
Complete history	See info



Registration #1	2007-07-05	23 mi
Registration #2	2010-07-05	14.241 mi
Registration #3	2011-07-04	19.022 mi
Registration #4	2012-07-04	23.346 mi
Registration #5	2013-07-03	28.525 mi
Registration #6	2014-07-02	33.419 mi
Registration #7	2015-06-29	38.236 mi
Registration #8	2016-07-01	43.204 mi
Registration #9	2017-07-05	47.928 mi
Registration #10	2017-07-05	47.928 mi
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		91.777 esi
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaeleeaule	naga 12/12

CarCheck.co.uk page 13/13

Number of seats	4
Number of axles	2
Engine number	BFS 056261