



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA CDTI 16V ELITE
Colour	Grey
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2021-08-25
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	10

MOT #17	2020-08-26 12:39
MOT test number	417639598167
Result	✓ Passed
Next expiry date	2021-08-25

MOT #16	2020-08-26 07:59
MOT test number	526054073172
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15	2019-08-13 12:56
MOT test number	897857158620
Result	✓ Passed

**MOT #14** 2019-06-08 15:40**MOT test number** 417234655438**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm , inner edge wear. (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge wear. (5.2.3 (e))**MOT #13** 2019-06-08 13:22**MOT test number** 190759472125**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm , inner edge wear. (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge wear. (5.2.3 (e))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2018-06-06 16:14**MOT test number** 966063776367**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-06-06 12:22**MOT test number** 759448975567**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2017-07-03 13:55**MOT test number** 986905341261**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Sill covers fitted engine cover & under tray**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #9** 2016-06-23 10:44**MOT test number** 987074954827**Result** ✓ Passed**MOT #8** 2015-06-18 14:20**MOT test number** 205989065121**Result** ✓ Passed**MOT #7** 2014-06-30 14:23**MOT test number** 597021084185**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #6** 2013-06-06 11:46**MOT test number** 985907253198**Result** ✓ Passed**MOT #5** 2012-05-28 10:17**MOT test number** 626559442160**Result** ✓ Passed

**MOT #4** 2011-06-09 10:33**MOT test number** 366420561113**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**MOT #3** 2011-05-31 15:02**MOT test number** 207141951110**Result** ✗ Failed**Advice** Nearside Rear position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**MOT #2** 2010-05-26 13:53**MOT test number** 850576040102**Result** ✓ Passed**MOT #1** 2010-05-26 12:05**MOT test number** 813546240153**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
31 August 2021

✕
MOT

Expired:
25 August 2021

Tax status	Expired at 31 August 2021
Days left	973 days too late
MOT expiry date	25 August 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KC07SDU
Plate since	2024-03-28
Current registration	 KC07SDU
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-31
Last registration	2020-08-26
Complete history	See info



Registration #1	2007-05-31	8 mi
Registration #2	2010-05-26	35.581 mi
Registration #3	2010-05-26	35.581 mi
Registration #4	2011-05-31	45.059 mi
Registration #5	2011-06-09	45.086 mi
Registration #6	2012-05-28	50.855 mi
Registration #7	2013-06-06	54.750 mi
Registration #8	2014-06-30	57.306 mi
Registration #9	2015-06-18	58.798 mi
Registration #10	2016-06-23	60.976 mi
Registration #11	2016-06-23	60.976 mi
Registration #12	2016-06-23	60.976 mi
Registration #13	2016-06-23	60.976 mi
Registration #14	2016-06-23	60.976 mi
Registration #15	2016-06-23	60.976 mi
Registration #16	2016-06-23	60.976 mi
Registration #17	2016-06-23	60.976 mi
Registration #18	2016-06-23	60.976 mi
Registration #19	2016-06-23	60.976 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1466 mm
Length	4636 mm
Wheel base	2830 mm
Kerb weight	1587 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	17197285