





report date: 2024-03-29

General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 206 LX |
| Colour | Grey |
| Year of manufacture | 2003 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 111 Nm at 2.600 rpm |
| Engine capacity | 1.360 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.2 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 39.2 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-06-14

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

| MOT expiry date | 2022-06-17 |
|--------------------|------------|
| MOT pass rate | 76 % |
| MOT passed | 16 |
| Failed MOT tests | 5 |
| Total advice items | 27 |
| Total items failed | 7 |

| MOT #21 | 2021-06-18 12:26 |
|------------------|------------------|
| MOT test number | 489675537774 |
| Result | ✓ Passed |
| Next expiry date | 2022-06-17 |

| MOT #20 | 2020-07-16 09:14 |
|-----------------|------------------|
| MOT test number | 482009914735 |
| Result | ✓ Passed |

| MOT #19 | 2019-07-10 08:29 |
|--|------------------|
| MOT test number | 770965770107 |
| Result | ✓ Passed |
| Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |

| MOT #18 | 2018-07-13 08:45 |
|--|------------------|
| MOT test number | 209599794202 |
| Result | ✓ Passed |
| Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #17 | 2017-07-13 11:14 |
|-----------------|------------------|
| MOT test number | 711638135146 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/14



MOT #16

Result

NH03OCJ report date: 2024-03-29

2016-07-14 14:08

X Failed

MOT test number 251464971193

Result ✓ Passed

Advice Brake pipe slightly corroded both front to rears (3.6.B.2c)

MOT #15 2016-07-14 08:46

MOT test number 982286017926

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Brake pipe slightly corroded both front to rears (3.6.B.2c)

MOT #14 2015-07-09 13:37

MOT test number 239500395152

Result

Passed

Advice Coil spring corroded (2.4.C.1b)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Brake hose has slight corrosion to ferrules (3.6.B.4e)

Notice Tyres are cracked and perished and both front are scrubbed on inner edge

Notice Under-trays fitted obscuring some underside components

Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Offside Front Macpherson strut has slight movement in the upper support bearing assembly

Notice Rear axle has slight camber

(2.5.B.1b)

CarCheck.co.uk page 4/14



NH03OCJ

report date: 2024-03-29

MOT #13 2015-07-09 11:17 586690995151 **MOT** test number Result × Failed **Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)Notice Rear axle has slight camber Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Notice Engine covers fitted obscuring some components in the engine bay Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4) Advice Exhaust has a minor leak of exhaust gases (7.1.2) Notice Tyres are cracked and perished and both front are scrubbed on inner edge Notice Under-trays fitted obscuring some underside components Advice Coil spring corroded (2.4.C.1b) Advice Brake hose has slight corrosion to ferrules (3.6.B.4e)

| MOT #12 | | 2014-07-17 14:37 |
|----------|--|------------------|
| MOT test | number | 248368794496 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Offside Front Suspension arm has slight play in a ball joint (2.4.G.2) | |

| Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2) | | |
|---|------------------|--|
| MOT #11 | 2013-07-23 13:49 | |
| MOT test number | 459884203281 | |
| Result | ✓ Passed | |
| | | |
| MOT #10 | 2012-07-19 14:43 | |
| MOT test number | 277701602284 | |
| Result | ✓ Passed | |

CarCheck.co.uk page 5/14



MOT #9 2012-07-19 14:43

MOT test number 225201602224

Result X Failed

Pass with rectification Offside Headlamp aim too low (1.8)

Pass with rectification Nearside Headlamp aim too high (1.8)

MOT #8 2011-07-22 13:28

MOT test number 325003801235

Result ✓ Passed

MOT #7 2011-07-19 14:37

MOT test number 427760201265

Result X Failed

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6 2010-07-06 11:42

MOT test number 392517980183

Result

Passed

MOT #5 2010-07-01 11:43

MOT test number 493362880106

Result × Failed

Fail Nearside Front coil spring fractured (2.4.C.1a)

MOT #4 2009-07-07 11:30

MOT test number 234868389139

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 6/14



Advice

NH03OCJ report date: 2024-03-29

MOT #3 2008-07-08 15:01 **MOT test number** 211230798458 Result ✓ Passed MOT #2 2007-07-12 09:50 **MOT** test number 280493897475 Result ✓ Passed MOT #1 2006-07-14 09:40 **MOT test number** 980745396104 Result ✓ Passed **Advice** Nearside Tyre worn close to the legal limit (4.1.E.1) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



Tax & MOT check



Х МОТ

Expired: 17 June 2022

| Tax status | Expired at 11 June 2022 |
|------------------|-------------------------|
| Days left | 689 days too late |
| MOT expiry date | 17 June 2022 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



NH03OCJ

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



NH03OCJ

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. door of plates factor scincol

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2003-07-30 |
| Last registration | 2021-06-18 |
| Complete history | See info |



| Registration #1 | 2003-07-30 | 24 mi |
|------------------|------------|-----------|
| Registration #2 | 2006-07-14 | 22.313 mi |
| Registration #3 | 2007-07-12 | 29.167 mi |
| Registration #4 | 2008-07-08 | 35.531 mi |
| Registration #5 | 2009-07-07 | 42.673 mi |
| Registration #6 | 2010-07-01 | 49.130 mi |
| Registration #7 | 2010-07-06 | 49.132 mi |
| Registration #8 | 2011-07-19 | 55.322 mi |
| Registration #9 | 2011-07-22 | 55.343 mi |
| Registration #10 | 2012-07-19 | 60.196 mi |
| Registration #11 | 2013-07-23 | 63.977 mi |
| Registration #12 | | 11.117 es |
| Registration #13 | | 11.177 es |
| Registration #14 | | 11.117 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.177 mi |
| Registration #18 | | 11.177 es |
| Registration #19 | | 11.177 es |
| Registration #20 | | 11.177 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.777 es |
| | | |

More info >

CarCheck.co.uk page 13/14



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | *** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1652 mm |
|-------------|---------|
| Height | 1433 mm |
| Length | 3822 mm |
| Wheel base | 2445 mm |
| Kerb weight | 950 kg |

Additional information

| Fuel tank capacity | 50 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Engine number | FSI24469875 |

CarCheck.co.uk page 14/14