



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI DSG 105
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-29
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-20
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	49
Total items failed	0

MOT #17	2023-10-20 14:27
MOT test number	441266182420
Result	✓ Passed
Next expiry date	2024-10-20
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2023-10-20 11:15
MOT test number	997944291934
Result	✗ Failed
MAJOR	Offside Side repeater not working (4.4.1 (a) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
MAJOR	Nearside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))

MOT #15	2022-10-21 14:02
MOT test number	289062724097
Result	✓ Passed

**MOT #14**

2022-10-21 10:38

**MOT test number**

402246122616

**Result****✗ Failed**

- MAJOR** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**MOT #13**

2021-09-03 11:20

**MOT test number**

964283298504

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing slightly uneven tread and perished (5.2.3 (d) (ii))

**MOT #12**

2020-08-27 08:29

**MOT test number**

685693780343

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing heavily perished and cracking (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and splitting (5.3.4 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and splitting (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11**

2019-08-19 13:38

**MOT test number**

872073484582

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect misting of oil (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and cracking (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and cracking (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished and cracking (5.2.3 (d) (ii))

**MOT #10**

2019-08-19 09:19

**MOT test number**

583964115530

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished and cracking (5.2.3 (d) (ii))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and cracking (5.3.4 (a) (i))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect misting of oil (5.3.2 (b))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished and cracking (5.3.4 (a) (i))

**MOT #9**

2018-09-03 14:21

**MOT test number**

126296142658

**Result****✓ Passed**

- Advice** Covers and under trays fitted some under vehicle components not checked
- Advice** Engine covers and under trays fitted some under bonnet components not checked

**MOT #8**

2018-08-30 08:20

**MOT test number**

986374315552

**Result****✗ Failed**

- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Covers and under trays fitted some under vehicle components not checked
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Engine covers and under trays fitted some under bonnet components not checked
- MAJOR** Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))



**MOT #7** 2017-09-01 13:32**MOT test number** 119857627954**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-08-30 10:08**MOT test number** 818463379454**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre worn on edges**MOT #5** 2015-08-12 10:56**MOT test number** 426184325269**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-08-18 09:53**MOT test number** 648110534246**Result** ✓ Passed**MOT #3** 2013-08-20 11:34**MOT test number** 646832633276**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-08-31 12:06**MOT test number** 318754542261**Result** ✓ Passed





MOT #1	2011-08-08 09:59
MOT test number	209780821258
Result	✓ Passed
<div>Notice</div> Nearside front driveshaft inner cv gaitor leaking	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
20 October 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	20 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FN58OMK</b>
Plate since	2019-06-29
Current registration	 <b>FN58OMK</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-03
Last registration	2023-10-20
Complete history	<a href="#">See info</a>



Registration #1	2008-09-03	9 mi
Registration #2	2011-08-08	30.488 mi
Registration #3	2012-08-31	34.503 mi
Registration #4	2013-08-20	38.249 mi
Registration #5	2014-08-18	41.822 mi
Registration #6	2015-08-12	46.659 mi
Registration #7	2016-08-30	54.710 mi
Registration #8	2017-09-01	66.057 mi
Registration #9	2018-08-30	75.719 mi
Registration #10	2018-09-03	75.827 mi
Registration #11	2019-09-03	75.827 mi
Registration #12	2019-09-03	75.827 mi
Registration #13	2019-09-03	75.827 mi
Registration #14	2019-09-03	75.827 mi
Registration #15	2019-09-03	75.827 mi
Registration #16	2019-09-03	75.827 mi
Registration #17	2019-09-03	75.827 mi
Registration #18	2019-09-03	75.827 mi
Registration #19	2019-09-03	75.827 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1301 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5



Number of seats	5
Number of axles	2
Engine number	BXE A26589