



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	Black
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-08
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	29
Total items failed	5

MOT #12	2024-01-27 13:00
MOT test number	771243788759
Result	✓ Passed
Next expiry date	2025-02-08
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Covers fitted obscuring some components

MOT #11	2024-01-27 10:25
MOT test number	150717594577
Result	✗ Failed
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Covers fitted obscuring some components

MOT #10	2023-02-03 09:19
MOT test number	591275462377
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2023-02-03 09:19

MOT test number

519476723729

Result**✗ Failed****Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8**

2022-01-24 08:22

MOT test number

348651344893

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Undertray fitted**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2021-02-09 10:02

MOT test number

312730443179

Result**✓ Passed****Advice** Undertray fitted

**MOT #6**

2021-02-05 15:18

MOT test number

590180410804

Result

✗ Failed

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Undertray fitted**Advice** Rear wiper split**Fail** Nearside Front Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** TPM on**MOT #5**

2020-08-25 15:38

MOT test number

261435851713

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing walls cracking (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing walls cracking (5.2.3 (d) (ii))**Advice** Tyre pressure light on**MOT #4**

2020-08-25 10:10

MOT test number

570687168019

Result

✗ Failed

Advice Tyre pressure light on**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing walls cracking (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing walls cracking (5.2.3 (d) (ii))



MOT #3	2019-08-12 08:46
MOT test number	675473176493
Result	✓ Passed

MOT #2	2018-08-16 16:02
MOT test number	671093086480
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2017-08-30 12:57
MOT test number	277045276907
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX64EFO
Plate since	2019-03-29
Current registration	EX64EFO
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-01
Last registration	2024-01-27
Complete history	See info



Registration #1	2014-09-01	26 mi
Registration #2	2017-08-30	27.829 mi
Registration #3	2018-08-16	33.473 mi
Registration #4	2019-08-12	44.429 mi
Registration #5	2020-08-25	58.090 mi
Registration #6	2020-08-25	58.090 mi
Registration #7	2021-08-25	58.090 mi
Registration #8	2022-08-25	58.090 mi
Registration #9	2023-08-25	58.090 mi
Registration #10	2024-01-27	58.090 mi
Registration #11	2024-01-27	58.090 mi
Registration #12	2024-01-27	58.090 mi
Registration #13	2024-01-27	58.090 mi
Registration #14	2024-01-27	58.090 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FDEZ867300