





report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-08

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-05-31
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #13	2023-05-31 08:01
MOT test number	692033686407
Result	✓ Passed
Next expiry date	2024-05-31
Advice Nearside Front Tyre slightly damaged/cracking or perishing cracks in	side wall (5.2.3 (d) (ii))

MOT #12	2022-06-01 09:1
MOT test	number 18751914906
Result	✓ Passe
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge wear and cracking (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11

MOT test number

664103354817

Result

Advice Rear exhaust outer skin corroded

Advice Rear shockers corroded

MOT #10

MOT test number

Result

Advice Rear shock absorbers corroded

Advice Rear exhaust corroded

Advice Fluid leak, but not excessive (8.4.1 (a) (i))

MOT #9 2020-07-07 08:07 625258798998 **MOT** test number Result × Failed Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Fluid leak, but not excessive (8.4.1 (a) (i)) Advice Rear exhaust corroded Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Rear shock absorbers corroded **Advice**

 MOT #8
 2019-05-10 08:05

 MOT test number
 963724486924

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7 2018-03-08 12:40

MOT test number 765353142488

MOT #6 2017-02-28 11:01

MOT test number 259318919805

Result Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2016-03-07 10:09

MOT test number 265053323054

Result Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2015-02-19 13:00

MOT test number 438340655013

Result \square Passed

MOT #3 2015-02-19 11:37

MOT test number 535970255052

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #2 2014-03-05 11:47

MOT test number 516804464004

Result ✓ Passed

MOT #1 2013-03-11 10:54

MOT test number 846490373091

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

Plate changes	More info >
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-10
Last registration	2023-05-31
Complete history	See info



Registration #1	2010-03-10	23 mi
Registration #2	2013-03-11	15.568 mi
Registration #3	2014-03-05	22.704 mi
Registration #4	2015-02-19	26.852 mi
Registration #5	2015-02-19	26.856 mi
Registration #6	2016-03-07	29.066 mi
Registration #7	2017-02-28	592 mi
Registration #8	2018-03-08	5.419 mi
Registration #9		11.777 es
Registration #10		77,777 66
Registration #11		11.177 es
Registration #12		D.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		9.777 no

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 5775203