



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 SE
Colour	Red
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-10
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2021-09-08 07:50
<b>MOT test number</b>	697667171938
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-01
<b>Advice</b>	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #17</b>	2020-10-02 13:24
<b>MOT test number</b>	378904185382
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #16</b>	2020-10-02 09:36
<b>MOT test number</b>	232001399968
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>MAJOR</b>	Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
<b>DANGEROUS</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #15</b>	2019-09-14 08:52
<b>MOT test number</b>	973521026830
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
<b>Advice</b>	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement LOWER ARM REAR BUSH (5.3.4 (a) (i))
<b>Advice</b>	Oil leak, but not excessive GEAR BOX (8.4.1 (a) (i))



<b>MOT #14</b>	2018-09-14 10:22
<b>MOT test number</b>	618449614131
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake fluid close to minimum mark (1.1.10 (d) (ii))

<b>MOT #13</b>	2018-09-07 10:51
<b>MOT test number</b>	293530712404
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Nearside Rear Seat belt buckle not functioning as intended unable to test due to object stuck in clasp (7.1.2 (d))
<b>MAJOR</b>	Offside Front Headlamp aim too low (4.1.2 (a))
<b>MAJOR</b>	Offside Rear Tyre(s) of different sizes are fitted on the same axle. tyre is the wrong size (5.2.3 (b))
<b>MAJOR</b>	Nearside Front Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Brake fluid close to minimum mark (1.1.10 (d) (ii))
<b>MAJOR</b>	Offside Front Suspension arm pin or bush excessively worn wishbone rear bush has excessive movement (5.3.4 (a) (i))

<b>MOT #12</b>	2017-09-01 07:55
<b>MOT test number</b>	813826835855
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit getting low on inner edge (4.1.E.1)

**MOT #11** 2017-08-31 08:36**MOT test number** 751024098198**Result** ✗ Failed**Fail** Nearside Rear brake caliper leaking (3.6.A.1)**Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit getting low on inner edge (4.1.E.1)**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)**MOT #10** 2016-08-16 16:13**MOT test number** 470816608590**Result** ✓ Passed**MOT #9** 2016-08-16 12:05**MOT test number** 747306369214**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #8** 2016-01-16 11:41**MOT test number** 144266673548**Result** ✓ Passed**MOT #7** 2015-01-16 16:55**MOT test number** 406396715021**Result** ✓ Passed

**MOT #6** 2015-01-16 15:21**MOT test number** 555956915039**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-01-10 15:43**MOT test number** 689900914079**Result** ✓ Passed**MOT #4** 2013-05-01 13:45**MOT test number** 788261823151**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-09-08 12:10**MOT test number** 729312452267**Result** ✓ Passed**MOT #2** 2011-08-05 09:51**MOT test number** 338827511226**Result** ✓ Passed**MOT #1** 2010-07-22 15:33**MOT test number** 164653800238**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-08-02
Last registration	2021-09-08
Complete history	<a href="#">See info</a>



Registration #1	2007-08-02	19 mi
Registration #2	2010-07-22	70.631 mi
Registration #3	2011-08-05	93.321 mi
Registration #4	2012-09-08	99.001 mi
Registration #5	2013-05-01	104.073 mi
Registration #6	2014-01-10	110.924 mi
Registration #7	2015-01-16	117.323 mi
Registration #8	2015-01-16	117.232 mi
Registration #9	2016-01-16	123.340 mi
Registration #10	2016-08-16	126.585 mi
Registration #11	2016-08-16	126.585 mi
Registration #12	2016-08-16	126.585 mi
Registration #13	2016-08-16	126.585 mi
Registration #14	2016-08-16	126.585 mi
Registration #15	2016-08-16	126.585 mi
Registration #16	2016-08-16	126.585 mi
Registration #17	2016-08-16	126.585 mi
Registration #18	2016-08-16	126.585 mi
Registration #19	2016-08-16	126.585 mi
Registration #20	2016-08-16	126.585 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1328 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	73027