





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE BUSINESS TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2017
Top speed	135 mph
0 - 100 km/h	8.9 seconds
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-29

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



DC170YE report date: 2024-03-29

MOT history

MOT expiry date	2024-11-15
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #8		2023-11-16 11:27
MOT test	number	831795611162
Result		✓ Passed
Next expi	y date	2024-11-15
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge worn	smooth (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2023-05-22 12:33
MOT test number	258152363955
Result	✓ Passed
MOT #6	2022-05-30 14:28
MOT test number	840616397930
Result	✓ Passed

MOT #5		2022-03-31 14:14
MOT test	number	863156926127
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Items removed from driver's view prior to test

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number
920510376656

Result
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Items removed from driver's view prior to test

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #2 2020-07-30 09:35 152918042637 **MOT** test number Result Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e)) Advice Nearside Front Nail in tyre Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e)) Advice Tpms light on Advice Offside Rear Nail in tyre

MOT #1

MOT test number

979661963594

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



DC170YE report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



DC170YE report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Category

Туре

Date



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



DC170YE report date: 2024-03-29

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

manage and a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	IIK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-31
Last registration	2023-11-16
Complete history	See info



Registration #1	2017-07-31	28 mi
Registration #2	2020-07-30	68.500 mi
Registration #3	2021-07-20	77.206 mi
Registration #4	2021-07-20	77.206 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1505 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	5
CarChock co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CRLB730395