




General information

Make	VOLKSWAGEN
Model	EOS FSI DSG SPORT (250BHP)
Colour	Silver
Year of manufacture	2006
Top speed	154 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	247 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	3.189 cc
Cylinders	6
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.7 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-10
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-03-10
<b>MOT pass rate</b>	79 %
<b>MOT passed</b>	15
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	31
<b>Total items failed</b>	8

**MOT #19** 2024-03-11 15:38**MOT test number** 961421996722**Result** Passed**Next expiry date** 2025-03-10**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Wingmirror damaged but not likely to cause injury**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2022-11-15 14:44**MOT test number** 778215059419**Result** Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))**MOT #17** 2021-10-15 11:01**MOT test number** 649767673243**Result** Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2020-10-13 13:32**MOT test number** 467103321788**Result** ✓ Passed**Advice** Offside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #15** 2019-10-17 15:19**MOT test number** 883316366646**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2 mm bald on inner edge (5.2.3 (e))**MOT #14** 2019-10-16 14:40**MOT test number** 588258673473**Result** ✗ Failed**Fail** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.3 (a))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2 mm bald on inner edge (5.2.3 (e))**MOT #13** 2018-09-28 08:54**MOT test number** 142286723191**Result** ✓ Passed

**MOT #12** 2018-09-27 11:08**MOT test number** 323215199436**Result** ✗ Failed

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #11** 2017-09-26 09:31**MOT test number** 399131808963**Result** ✓ Passed

**Advice** Advise engine covers fitted unable to fully inspect engine bay

**Advice** Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Advise nearside rear shock absorber plastic cover insecure

**Advice** Advise under tray fitted unable to fully inspect front

**Advice** Advise slight leak on washers pipe

**MOT #10** 2016-09-12 13:55**MOT test number** 665765621262**Result** ✓ Passed

**Advice** 2. Rear brake discs starting to corrode.

**Advice** 1. Slight damage to front windscreen.

**MOT #9** 2015-09-28 12:33**MOT test number** 375373369994**Result** ✓ Passed



<b>MOT #8</b>	2015-03-19 10:24
<b>MOT test number</b>	329718875008
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #7</b>	2015-03-18 14:34
<b>MOT test number</b>	205797975072
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #6</b>	2014-02-27 11:30
<b>MOT test number</b>	367738454038
<b>Result</b>	✓ Passed
<b>Notice</b>	Nearside door mirror assembly slightly loose
<b>Notice</b>	Front tyre inner sidewalls cracking on surfaces

<b>MOT #5</b>	2014-02-26 16:43
<b>MOT test number</b>	589937254055
<b>Result</b>	✗ Failed
<b>Notice</b>	Nearside door mirror assembly slightly loose
<b>Notice</b>	Front tyre inner sidewalls cracking on surfaces
<b>Fail</b>	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)



MOT #4	2013-03-01 16:37
MOT test number	839450463080
Result	✓ Passed
MOT #3	2012-03-01 14:43
MOT test number	668021262067
Result	✓ Passed
MOT #2	2010-10-25 10:25
MOT test number	602318590299
Result	✓ Passed
MOT #1	2009-11-19 09:17
MOT test number	741243129359
Result	✓ Passed
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	High level stop light inop if it is wired in it must work
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
10 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	10 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-12-14
Last registration	2024-03-11
Complete history	<a href="#">See info</a>



Registration #1	2006-12-14	14 mi
Registration #2	2009-11-19	31.129 mi
Registration #3	2010-10-25	31.450 mi
Registration #4	2012-03-01	31.823 mi
Registration #5	2013-03-01	37.044 mi
Registration #6	2014-02-26	40.434 mi
Registration #7	2014-02-27	40.450 mi
Registration #8	2015-03-18	45.785 mi
Registration #9	2015-03-19	45.785 mi
Registration #10	2015-09-28	46.676 mi
Registration #11	2016-09-12	52.688 mi
Registration #12	2016-09-12	52.688 mi
Registration #13	2016-09-12	52.688 mi
Registration #14	2016-09-12	52.688 mi
Registration #15	2016-09-12	52.688 mi
Registration #16	2016-09-12	52.688 mi
Registration #17	2016-09-12	52.688 mi
Registration #18	2016-09-12	52.688 mi
Registration #19	2016-09-12	52.688 mi
Registration #20	2016-09-12	52.688 mi
Registration #21	2016-09-12	52.688 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	BUB022684