



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | CITROEN |
| Model | C1 PURETECH FLAIR |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 106 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 82 BHP |
| Max. torque | 116 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 52.3 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-03-04 |
| Pictures | 1 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-30 |
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| | |
|------------------|------------------|
| MOT #5 | 2024-01-25 13:20 |
| MOT test number | 221354910218 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-30 |

| | |
|-----------------|------------------|
| MOT #4 | 2023-01-12 09:33 |
| MOT test number | 516482108900 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #3 | 2022-01-25 08:59 |
| MOT test number | 945731156865 |
| Result | ✓ Passed |

Advice Rear Tyre slightly damaged/cracking or perishing Both rear tyres slightly perished. (5.2.3 (d) (ii))

Minor Windscreen wiper blade defective (3.4 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres 3mm. (5.2.3 (e))

| | |
|-----------------|------------------|
| MOT #2 | 2021-01-18 15:12 |
| MOT test number | 246085719530 |
| Result | ✓ Passed |

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #12021-01-18 11:14

MOT test number421541933345

| Result | | ✗ Failed |
|--------|---|----------|
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Exhaust mounting defective (6.1.2 (a)) | |
| Fail | Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
30 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 30 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,000 |
| Auction value | £ 15,000 |
| Average private trade value | £ 15,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 7 |
| First mileage registration | 2018-01-31 |
| Last registration | 2024-01-25 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-01-31 | 26 mi |
| Registration #2 | 2021-01-18 | 21.105 mi |
| Registration #3 | 2021-01-18 | 21.105 mi |
| Registration #4 | 2022-01-20 | 21.105 mi |
| Registration #5 | 2022-01-20 | 21.105 mi |
| Registration #6 | 2022-01-20 | 21.105 mi |
| Registration #7 | 2022-01-20 | 21.105 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★ |
| Adult | 68% |
| Children | 73% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 66% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1615 mm |
| Height | 1460 mm |
| Length | 3465 mm |
| Wheel base | 2340 mm |
| Kerb weight | 865 kg |
| Max. allowed weight | 1240 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | B2220061493 |