



General information

Make	FORD
Model	FUSION ZETEC
Colour	Grey
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-01-22
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-26
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	53
Total items failed	15

MOT #16	2023-06-27 07:54
MOT test number	224864927196
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Offside Rear Tyre slightly damaged/cracking or perishing deep cracks in tread (5.2.3 (d) (ii))
Advice	Headlamp brackets repaired badly
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Body panel slightly loose arch trim (6.2.1 (a) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Body panel slightly loose bumper corner (6.2.1 (a) (i))

**MOT #15**

2023-06-26 13:53

**MOT test number**

576555003525

**Result****✗ Failed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Front Lower Body panel insecure wheel arch (6.2.1 (a) (i))**Advice** Nearside Rear Body panel slightly loose arch trim (6.2.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing deep cracks in tread (5.2.3 (d) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Front Bumper insecure grill loose (6.1.4 (a) (i))**Advice** Offside Rear Body panel slightly loose bumper corner (6.2.1 (a) (i))**Advice** Headlamp brackets repaired badly**Fail** Nearside Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))**MOT #14**

2022-07-23 11:10

**MOT test number**

590076932434

**Result****✓ Passed****Advice** Front Both side headlamp top bracket broken.**Advice** Offside Rear Tyre has crack.**Advice** Offside Front Fog lamp cover missing.

**MOT #13**

2022-07-23 08:51

**MOT test number**

276218177937

**Result**

✗ Failed

**Advice** Nearside Rear Nail in tyre Multiple.**Fail** Offside Front Windscreen washer not working (3.5 (a))**Pass with rectification** Front Headlamp aim too low Both side. (4.1.2 (a))**Advice** Rear Both tyre has crack.**Advice** Front Both side headlamp top bracket broken.**Advice** Offside Front Fog lamp cover missing.**Advice** Items removed from driver's view prior to test**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** High level stop lamp not working.**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Wing trim insecure.**MOT #12**

2021-07-17 08:19

**MOT test number**

408319720901

**Result**

✓ Passed

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 2x nails in tread (5.2.3 (d) (ii))

**MOT #11** 2020-07-28 13:21**MOT test number** 519993111759**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2019-07-15 14:49**MOT test number** 238711952079**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Advice** Nearside Rear Nail in tyre**MOT #9** 2019-07-15 10:55**MOT test number** 921272878475**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Front Tyre tread depth below requirements of 1.6mm both side (5.2.3 (e))**Fail** Nearside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

**MOT #8** 2018-07-09 16:16**MOT test number** 194722199934**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-07-06 08:29**MOT test number** 512689823321**Result** ✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Rear fog lamp light intensity significantly reduced (4.5.4 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2017-07-14 11:11**MOT test number** 591576522989**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 195-60-15 (4.1.E.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #5** 2016-07-19 10:56**MOT test number** 423934526211**Result** ✓ Passed**MOT #4** 2016-07-19 10:56**MOT test number** 916330781327**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2015-08-11 11:02**MOT test number** 406273125288**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #2** 2014-07-22 10:04**MOT test number** 219423304231**Result** ✓ Passed





MOT #1	2013-07-27 10:43
MOT test number	616078203227
Result	✓ Passed
<div><div>Advice</div>Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div> <div><div>Advice</div>Nearside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)</div> <div><div>Notice</div>Engine covers fitted obscuring some components in the engine bay</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
26 June 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	26 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>LY10HCH</b>
Plate since	2019-03-29
Current registration	<b>LY10HCH</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-26
Last registration	2023-06-27
Complete history	<a href="#">See info</a>



Registration #1	2010-07-26	16 mi
Registration #2	2013-07-27	13.809 mi
Registration #3	2014-07-22	18.074 mi
Registration #4	2015-08-11	19.786 mi
Registration #5	2016-07-19	22.868 mi
Registration #6	2016-07-19	22.868 mi
Registration #7	2017-07-14	26.954 mi
Registration #8	2018-07-06	29.491 mi
Registration #9	2018-07-09	29.491 mi
Registration #10	2019-06-20	35.377 mi
Registration #11	2019-06-20	35.377 mi
Registration #12	2019-06-20	35.377 mi
Registration #13	2019-06-20	35.377 mi
Registration #14	2019-06-20	35.377 mi
Registration #15	2019-06-20	35.377 mi
Registration #16	2019-06-20	35.377 mi
Registration #17	2019-06-20	35.377 mi
Registration #18	2019-06-20	35.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1170 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



Number of axles	2
Engine number	AU80235