



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH COMBI L1H1 6 HDI 90
Colour	Silver
Year of manufacture	2010
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	39.2 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-02-08
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	30
Total items failed	17

MOT #122019-07-06 09:56

MOT test number276671348738

Result✓ Passed

Next expiry date2021-01-05

- AdviceElectrical plug on engine disconnected possible oil pressure switch?
- AdviceNearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- AdviceNearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceNearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- AdviceOffside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceOffside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2019-06-22 11:08

MOT test number

202497709136

Result

✗ Failed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Electrical plug on engine disconnected possible oil pressure switch?
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-06-18 15:51

MOT test number

455802649553

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Both front and rear discs lipped
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both front "D" bushes (5.3.4 (a) (i))
- Advice** A plug is disconnected on the engine that is believed to be for electric oil level sensor

**MOT #9** 2018-06-15 09:34**MOT test number** 406795076734**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Fail** Exhaust system insecure centre pipe (6.1.2 (a))**Advice** Both front and rear discs lipped**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both front "D" bushes (5.3.4 (a) (i))**Fail** Exhaust system insecure back box (6.1.2 (a))**Advice** A plug is disconnected on the engine that is believed to be for electric oil level sensor**MOT #8** 2017-06-19 14:45**MOT test number** 712453126184**Result** ✓ Passed**MOT #7** 2016-01-12 10:02**MOT test number** 996922870875**Result** ✓ Passed

**MOT #6** 2016-01-12 10:02**MOT test number** 222796732642**Result** ✗ Failed

- Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #5 2015-01-12 17:19**MOT test number** 827852915016**Result** ✓ Passed**MOT #4** 2014-01-17 11:49**MOT test number** 659867314050**Result** ✓ Passed**MOT #3** 2014-01-17 11:49**MOT test number** 436727914021**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

MOT #2 2013-01-23 12:08**MOT test number** 568023223032**Result** ✓ Passed



MOT #12013-01-23 12:08

MOT test number109603923032

Result

Failed

- Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

X

Untaxed

Tax expired:
16 August 2023

X

MOT

Expired:
8 February 2024

Tax status	Expired at 16 August 2023
Days left	257 days too late
MOT expiry date	8 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-02-06
Last registration	2019-07-06
Complete history	See info



Registration #1	2010-02-06	27 mi
Registration #2	2013-01-23	40.041 mi
Registration #3	2014-01-17	52.487 mi
Registration #4	2015-01-12	62.435 mi
Registration #5	2016-01-12	72.505 mi
Registration #6	2016-01-12	72.505 mi
Registration #7	2019-07-06	72.505 mi
Registration #8	2019-07-06	72.505 mi
Registration #9	2019-07-06	72.505 mi
Registration #10	2019-07-06	72.505 mi
Registration #11	2019-07-06	72.505 mi
Registration #12	2019-07-06	72.505 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	4805 mm
Wheel base	3000 mm
Kerb weight	1733 kg
Max. allowed weight	2710 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	6
Number of axles	2
Engine number	JBBY0018690