



NI3ICDP

report date: 2024-03-28

General information

Make	NISSAN
Model	SKYLINE
Colour	Silver
Year of manufacture	1996
Gearbox	-

Engine & fuel consumption

Engine capacity	2.490 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-07
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2023-04-06
<b>MOT pass rate</b>	63 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	66
<b>Total items failed</b>	4

**MOT #16** 2022-04-07 14:57**MOT test number** 333020797611**Result** ✓ Passed**Next expiry date** 2023-04-06

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Anti-roll bar modified but not seriously weakened (5.3.3 (c) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15** 2022-04-04 15:02**MOT test number** 865005397621**Result** ✗ Failed

- MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Anti-roll bar modified but not seriously weakened (5.3.3 (c) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-04-07 13:58

**MOT test number**

661508245478

**Result**

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central exhaust mount insecure
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front tyre perished

**MOT #13**

2021-03-31 09:51

**MOT test number**

189793657706

**Result**

✗ Failed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central exhaust mount insecure
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front tyre perished
- MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #12**

2018-10-01 13:31

**MOT test number**

785420067263

**Result**

✓ Passed

**Advice** Nearside Front Worn Inner edge 235/45/17**Advice** General surface corrosion under vehicle**Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement N/s & O/s (5.3.4 (a) (i))**MOT #11**

2018-09-29 12:05

**MOT test number**

890165803828

**Result**

✗ Failed

**Advice** Nearside Front Worn Inner edge 235/45/17**MAJOR** Hazard warning switch inoperative (4.4.2 (a) (ii))**Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement N/s & O/s (5.3.4 (a) (i))**Advice** General surface corrosion under vehicle**MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))



MOT #10

2017-02-23 12:18

MOT test number

269239593387

Result

✓ Passed

- Advice
- Offside Rear Track rod end ball joint has slight play (2.2.B.1f)
- Advice
- Exhaust not fully supported gearbox bracket
- Advice
- Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice
- Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice
- N/s/f tyre worn on inside edge
- Advice
- Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice
- Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice
- Wiper blades deteriorated
- Advice
- Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice
- Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice
- Rear wheel steering inoperative but rear wheels are held substantially in the straight ahead position and the steering is not adversely affected (2.2.B.1j)
- Advice
- Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice
- Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice
- Both headlight lenses deteriorated slightly effecting the beam pattern
- Advice
- Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #9**

2015-07-25 09:29

**MOT test number**

316906505258

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Front Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

**Advice** Offside Rear Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Advice** Offside Front Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #8**

2015-07-18 10:12

**MOT test number**

586069095172

**Result**

✗ Failed

**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)

**Advice** Offside Rear Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

**Advice** Offside Front Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Nearside Rear Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Nearside Front Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #7**

2014-04-30 12:07

**MOT test number**

298570624146

**Result**

✓ Passed

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**Advice** Brake pipe slightly corroded (3.6.B.2c)

**MOT #6** 2012-02-28 15:04**MOT test number** 147339852053**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-02-28 15:04**MOT test number** 908719952028**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2010-05-07 15:40**MOT test number** 103597620120**Result** ✓ Passed**MOT #3** 2010-05-06 12:19**MOT test number** 420566720163**Result** ✗ Failed**Notice** Offside Front Tyre Wearing On Inner Shoulder**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2009-01-23 15:24**MOT test number** 614193129082**Result** ✓ Passed





MOT #1	2008-02-02 17:35
MOT test number	392463738018
Result	✓ Passed
Notice	Near side rear tyre on legal limit
Notice	Front pads close to legal limit




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-02-02
Last registration	2022-04-07
Complete history	<a href="#">See info</a>



Registration #1	2008-02-02	39.948 mi
Registration #2	2009-01-23	47.854 mi
Registration #3	2010-05-06	51.724 mi
Registration #4	2010-05-07	51.724 mi
Registration #5	2012-02-28	55.712 mi
Registration #6	2014-04-30	61.357 mi
Registration #7	2015-07-18	65.192 mi
Registration #8	2015-07-25	65.198 mi
Registration #9	2016-05-20	65.197 mi
Registration #10	2016-05-20	65.197 mi
Registration #11	2016-05-20	65.197 mi
Registration #12	2016-05-20	65.197 mi
Registration #13	2016-05-20	65.197 mi
Registration #14	2016-05-20	65.197 mi
Registration #15	2016-05-20	65.197 mi
Registration #16	2016-05-20	65.197 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Additional information

Number of seats	5
Engine number	NOT KNOWN