



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180 KOMPRESSOR SPORT
Colour	Black
Year of manufacture	2007
Top speed	139 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	229 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.2 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	36
Total items failed	17

MOT #202024-04-03 12:20

MOT test number683952719208

Result✔ Passed

Next expiry date2025-04-04

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Rear subframe slight corrosion

**MOT #19**

2024-03-28 12:45

MOT test number

302718585234

Result

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Axle corroded
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Minor** Central Rear Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

2023-04-03 11:44

MOT test number

635956895154

Result

✓ Passed

MOT #17

2022-04-05 14:00

MOT test number

452760075293

Result

✓ Passed

- Advice** Brake disc worn, but not excessively all. (1.1.14 (a) (i))

**MOT #16** 2020-11-20 20:15**MOT test number** 353308311861**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2020-11-18 16:57**MOT test number** 152564545081**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-09-27 15:00**MOT test number** 978239804105**Result** ✓ Passed**MOT #13** 2018-10-09 11:55**MOT test number** 145634364158**Result** ✓ Passed**Advice** Corrosion on metal brake pipes**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Brake discs lipped

**MOT #12** 2017-10-05 11:06**MOT test number** 511823337144**Result** ✓ Passed

- Advice** Corrosion on o/s front metal brake pipe to flexi hose
- Advice** Front tyre at n/s wearing on edges
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11 2017-10-04 10:23**MOT test number** 396436733196**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front tyre at n/s wearing on edges
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Corrosion on o/s front metal brake pipe to flexi hose

MOT #10 2016-09-28 09:46**MOT test number** 596252099054**Result** ✓ Passed

- Advice** Corrosion on o/s front metal brake pipe

MOT #9 2016-09-28 09:46**MOT test number** 434684031681**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Corrosion on o/s front metal brake pipe

**MOT #8** 2015-09-22 16:02**MOT test number** 319248455986**Result** ✓ Passed**MOT #7** 2014-09-18 12:55**MOT test number** 379591664231**Result** ✓ Passed**MOT #6** 2013-09-03 16:06**MOT test number** 436876043234**Result** ✓ Passed**MOT #5** 2013-09-03 08:51**MOT test number** 399326943273**Result** ✗ Failed**Fail** Offside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2012-10-05 11:55**MOT test number** 896909072282**Result** ✓ Passed

**MOT #3** 2012-10-04 11:00**MOT test number** 765088172295**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #2** 2011-09-19 09:38**MOT test number** 729552361200**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2010-10-19 09:28**MOT test number** 501992990231**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-23
Last registration	2024-04-03
Complete history	See info



Registration #1	2007-11-23	18 mi
Registration #2	2010-10-19	32.146 mi
Registration #3	2011-09-19	39.216 mi
Registration #4	2012-10-04	50.536 mi
Registration #5	2012-10-05	50.538 mi
Registration #6	2013-09-03	60.454 mi
Registration #7	2013-09-03	60.457 mi
Registration #8	2014-09-18	67.927 mi
Registration #9	2015-09-22	75.634 mi
Registration #10	2016-09-28	84.958 mi
Registration #11	2016-09-28	84.958 mi
Registration #12	2016-09-28	84.958 mi
Registration #13	2016-09-28	84.958 mi
Registration #14	2016-09-28	84.958 mi
Registration #15	2016-09-28	84.958 mi
Registration #16	2016-09-28	84.958 mi
Registration #17	2016-09-28	84.958 mi
Registration #18	2016-09-28	84.958 mi
Registration #19	2016-09-28	84.958 mi
Registration #20	2016-09-28	84.958 mi
Registration #21	2016-09-28	84.958 mi
Registration #22	2016-09-28	84.958 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27195230993489