



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS D4D T3S
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	300 Nm at 2.400 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg



**MOT history**

MOT #16	2021-01-29 11:45
MOT test number	339367974159
Result	✓ Passed
Next expiry date	2022-02-16
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2020-02-03 12:40
MOT test number	164368033109
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material ALL (1.1.11 (c))

**MOT #14**

2020-01-30 11:35

MOT test number

317061597595

Result

✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Brake performance not tested rear brake pipe burst - no brakes (1.2.1 (g))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material ALL (1.1.11 (c))

MOT #13

2019-02-07 09:17

MOT test number

844525594684

Result

✓ Passed

- Advice** Body damage
- Advice** Both head lamps deteriorating
- Advice** Chip in screen

**MOT #12** 2019-02-07 09:17**MOT test number** 370417716361**Result** ✗ Failed**Advice** Both head lamps deteriorating**Advice** Chip in screen**Advice** Body damage**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #11** 2018-02-15 10:42**MOT test number** 524575112947**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear body damage**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2018-02-15 10:42**MOT test number** 821970658873**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear body damage

**MOT #9** 2017-02-17 09:20**MOT test number** 169482777850**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit edges (4.1.E.1)**MOT #8** 2016-01-29 17:29**MOT test number** 698011639953**Result** ✓ Passed**Advice** Offside and nearside front tyres close to legal limit**MOT #7** 2016-01-29 17:29**MOT test number** 322491298891**Result** ✗ Failed**Pass with rectification** Front position lamp(s) not working front (1.1.A.3b)**Advice** Offside and nearside front tyres close to legal limit**Pass with rectification** Registration plate lamp not working number (1.1.C.1d)**MOT #6** 2015-02-05 10:18**MOT test number** 698126735012**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Both front tyres starting to wear thin

**MOT #5** 2015-02-05 10:18**MOT test number** 647206235067**Result** ✗ Failed**Notice** Both front tyres starting to wear thin**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2014-02-06 09:34**MOT test number** 836397734079**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight body damage**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2013-02-06 10:57**MOT test number** 218327633074**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in nearside rear tyre**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Slight rear brake imbalance**Notice** Both front tyres starting to wear on outer edge**MOT #2** 2012-02-08 11:33**MOT test number** 189669132489**Result** ✓ Passed



MOT #1	2011-01-26 12:26
MOT test number	148166021076
Result	✓ Passed
Notice	Nsr tyre low
Notice	Osr tyre wearing on edge
Notice	Nsf and osf tyres worn smooth on edge close to limit



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	FB57KYW
Plate since	2024-03-29
Current registration	FB57KYW
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-02-11
Last registration	2021-01-29
Complete history	See info



Registration #1	2008-02-11	8 mi
Registration #2	2011-01-26	49.410 mi
Registration #3	2012-02-08	62.260 mi
Registration #4	2013-02-06	78.588 mi
Registration #5	2014-02-06	94.000 mi
Registration #6	2015-02-05	110.243 mi
Registration #7	2016-01-29	125.037 mi
Registration #8	2016-01-29	125.037 mi
Registration #9	2016-01-29	125.037 mi
Registration #10	2016-01-29	125.037 mi
Registration #11	2016-01-29	125.037 mi
Registration #12	2016-01-29	125.037 mi
Registration #13	2016-01-29	125.037 mi
Registration #14	2016-01-29	125.037 mi
Registration #15	2016-01-29	125.037 mi
Registration #16	2016-01-29	125.037 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1525 mm
Length	4715 mm
Wheel base	2700 mm
Kerb weight	1465 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4425341727