



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-11-06
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	7

MOT #14	2023-11-07 14:38
MOT test number	703897029056
Result	✓ Passed
Next expiry date	2024-11-06
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2023-11-02 09:39
MOT test number	219214546965
Result	✗ Failed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Position lamp not working sidelight (4.2.1 (a) (ii))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12	2022-11-04 14:54
MOT test number	266016013832
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge bald on inner edge (5.2.3 (e))

**MOT #11** 2021-10-23 11:07**MOT test number** 580902717117**Result** ✓ Passed**MOT #10** 2021-01-29 13:07**MOT test number** 755630177070**Result** ✓ Passed**MOT #9** 2020-01-30 10:51**MOT test number** 320099728754**Result** ✓ Passed**MOT #8** 2019-02-14 10:33**MOT test number** 471662604756**Result** ✓ Passed**Advice** Small cut to nearside rear tyre tread area**MOT #7** 2019-02-14 09:20**MOT test number** 856185119268**Result** ✗ Failed**Minor** Nearside Side repeater flashing more than 120 times a minute (4.4.4 (a))**Fail** Nearside Side repeater light intensity significantly reduced (4.4.3 (a))**Advice** Small cut to nearside rear tyre tread area**MOT #6** 2018-02-16 10:33**MOT test number** 946937849108**Result** ✓ Passed**Advice** Offside front tyre worn smooth on inner edge**Advice** Nearside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)

**MOT #5** 2017-01-17 09:20**MOT test number** 211652602461**Result** ✓ Passed**Advice** Nearside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside front tyre worn on inner edge**MOT #4** 2017-01-17 09:20**MOT test number** 226927289126**Result** ✗ Failed**Advice** Nearside Side repeater deteriorated, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside front tyre worn on inner edge**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2016-01-22 08:32**MOT test number** 399144863315**Result** ✓ Passed**MOT #2** 2016-01-22 08:31**MOT test number** 828887740552**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2015-02-10 09:52**MOT test number** 375591845003**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 November 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN61ZSO
Plate since	2019-09-28
Current registration	EN61ZSO
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-02-16
Last registration	2023-11-07
Complete history	See info



Registration #1	2012-02-16	10 mi
Registration #2	2015-02-10	22.413 mi
Registration #3	2016-01-22	28.345 mi
Registration #4	2016-01-22	28.345 mi
Registration #5	2017-01-17	34.720 mi
Registration #6	2017-01-17	34.720 mi
Registration #7	2018-02-16	40.894 mi
Registration #8	2019-02-14	45.432 mi
Registration #9	2019-05-29	50.377 mi
Registration #10	2019-05-29	50.377 mi
Registration #11	2019-05-29	50.377 mi
Registration #12	2019-05-29	50.377 mi
Registration #13	2019-05-29	50.377 mi
Registration #14	2019-05-29	50.377 mi
Registration #15	2019-05-29	50.377 mi
Registration #16	2019-05-29	50.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	D4HBBU542816
---------------	--------------