



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO R LINE TDI BLUEMOTION TECHNOLO
Colour	Blue
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	320 Nm at 3.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-09-19
Pictures	30
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-18
Pictures	0
Listing price	View report

source: heycar.co.uk

**MOT history**

MOT expiry date	2025-04-12
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #7	2024-04-10 08:57
MOT test number	478725138801
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2023-04-13 10:20
MOT test number	449345887273
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2022-04-12 15:10
MOT test number	567566811236
Result	✓ Passed

**MOT #4**

2022-04-12 08:00

MOT test number

772618128479

Result

✗ Failed

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3

2021-04-09 12:01

MOT test number

999875085101

Result

✓ Passed

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

2020-03-19 09:48

MOT test number

616518184747

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice

Rear tyres saw tooth wear

Advice

Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #1

2019-03-18 15:37

MOT test number

642413339773

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 April 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GF16HHU
Plate since	2019-06-29
Current registration	 GF16HHU
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-04-12
Last registration	2024-04-10
Complete history	See info



Registration #1	2016-04-12	28 mi
Registration #2	2019-03-18	28.957 mi
Registration #3	2020-03-19	41.762 mi
Registration #4	2021-04-09	50.373 mi
Registration #5	2022-03-20	55.277 mi
Registration #6	2023-03-20	55.277 mi
Registration #7	2023-03-20	55.277 mi
Registration #8	2023-03-20	55.277 mi
Registration #9	2023-03-20	55.277 mi
Registration #10	2024-04-10	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2080 mm
Height	1406 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1275 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2

Engine number

B147270