



Mercedes-Benz

LL100KG

report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 109 CDI LONG P/V
Colour	Silver
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-25
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	20
Total items failed	14

MOT #14	2023-06-15 10:52
MOT test number	135045547983
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2022-06-14 12:49
MOT test number	955746291394
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2022-06-14 08:44

MOT test number

614249106263

Result**✗ Failed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11

2021-06-26 07:34

MOT test number

411241662678

Result**✓ Passed**

- Advice** Rear diff unit mounting bushes deteriorated

MOT #10

2021-06-24 14:57

MOT test number

368108780795

Result**✗ Failed**

- Fail** Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Rear diff unit mounting bushes deteriorated
- Fail** Reversing lamp inoperative (4.6.1 (a))

**MOT #9** 2019-05-29 11:46**MOT test number** 342716541432**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-05-29 11:46**MOT test number** 376154818209**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #7** 2018-04-28 07:24**MOT test number** 864944703634**Result** ✓ Passed**MOT #6** 2018-04-25 15:57**MOT test number** 486833237880**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick both rear (3.5.1g)**Advice** Engine oil level below minimum .**Advice** Both rear differential mounting bushes worn and damaged.**Fail** Rear position lamp(s) incorrect colour rear lense damaged. (1.1.A.3e)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)**Advice** O/s/f window switch not working.**Advice** N/s/f side seat cover missing.

**MOT #5** 2016-07-26 11:28**MOT test number** 815762866751**Result** ✓ Passed**MOT #4** 2015-06-03 14:12**MOT test number** 956084355168**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-06-26 14:41**MOT test number** 778577574182**Result** ✓ Passed**MOT #2** 2013-06-25 12:29**MOT test number** 995416473101**Result** ✓ Passed**MOT #1** 2013-06-25 12:29**MOT test number** 836436873114**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
25 June 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		25 June 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-10
Last registration	2023-06-15
Complete history	See info



Registration #1	2010-06-10	23 mi
Registration #2	2013-06-25	22.935 mi
Registration #3	2014-06-26	31.029 mi
Registration #4	2015-06-03	37.085 mi
Registration #5	2016-07-26	46.046 mi
Registration #6	2018-04-25	56.110 mi
Registration #7	2018-04-28	56.110 mi
Registration #8	2019-05-29	60.597 mi
Registration #9	2020-06-29	65.077 mi
Registration #10	2021-06-29	65.077 mi
Registration #11	2022-06-29	65.077 mi
Registration #12	2023-06-29	65.077 mi
Registration #13	2024-06-29	65.077 mi
Registration #14	2025-06-29	65.077 mi
Registration #15	2026-06-29	65.077 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	64698051797731