



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVT-I GRANITE
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-07
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-05-16
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	43
Total items failed	17

MOT #19	2023-05-15 07:43
MOT test number	133548511023
Result	✓ Passed
Next expiry date	2024-05-16

**MOT #18**

2022-05-17 16:21

**MOT test number**

730884977748

**Result**

✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Advanced corrosion to underside of vehicle
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Inner Vehicle structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Advanced corrosion to front and rear brake and suspension components
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #17**

2021-05-14 14:12

**MOT test number**

816764107839

**Result**

✓ Passed

**MOT #16**

2020-04-21 08:52

**MOT test number**

383348041501

**Result**

✓ Passed

**MOT #15**

2019-05-14 14:28

**MOT test number**

151442405785

**Result**

✓ Passed

**MOT #14** 2018-05-16 10:58**MOT test number** 818053886649**Result** ✓ Passed**MOT #13** 2017-04-20 10:50**MOT test number** 946343333198**Result** ✓ Passed

- Advice** Nearside Front slight brake bind
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Vehicle structure has slight corrosion (6.1.B.2)
- Advice** Front slight brake bind
- Advice** Offside Front slight brake bind
- Advice** Nearside Rear Nail in tyre

**MOT #12** 2017-04-20 09:44**MOT test number** 551567584024**Result** ✗ Failed

- Advice** Front slight brake bind
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front slight brake bind
- Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)
- Advice** Nearside Front slight brake bind
- Advice** Nearside Rear Nail in tyre
- Advice** Rear Vehicle structure has slight corrosion (6.1.B.2)

**MOT #11**

2016-01-14 16:09

**MOT test number**

463782866697

**Result**

✓ Passed

**Advice**

Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10**

2015-07-06 15:43

**MOT test number**

277027285147

**Result**

✓ Passed

**Notice**

Child seat fitted not allowing full inspection of adult belt

**MOT #9**

2015-06-09 11:19

**MOT test number**

807160065153

**Result**

✗ Failed

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail**

Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**Fail**

Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

**Fail**

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail**

Emissions not tested (7.3.A.1)

**Fail**

Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

**Fail**

Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**Fail**

Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

**Fail**

Exhaust has a major leak of exhaust gases (7.1.2)

**Fail**

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Notice**

Child seat fitted not allowing full inspection of adult belt

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2014-04-25 15:00

**MOT test number**

116225814127

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Nearside Outer Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2014-04-24 16:10

**MOT test number**

718574614177

**Result**

✗ Failed

**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)

**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)

**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)

**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)

**Fail** Offside Rear coil spring broken (2.4.C.1a)

**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Advice** Nearside Outer Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)

**MOT #6**

2012-11-28 11:55

**MOT test number**

799243232371

**Result**

✓ Passed

**MOT #5** 2011-12-05 14:43**MOT test number** 678429131315**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2010-12-22 14:07**MOT test number** 431966750452**Result** ✓ Passed**Notice** Front brake discs rusty**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #3** 2009-08-24 10:25**MOT test number** 941356039200**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**MOT #2** 2008-10-15 16:22**MOT test number** 912689188264**Result** ✓ Passed**MOT #1** 2007-10-25 12:37**MOT test number** 270548197234**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
16 May 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	16 May 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-11-03
Last registration	2023-05-15
Complete history	<a href="#">See info</a>



Registration #1	2004-11-03	17 mi
Registration #2	2007-10-25	30.696 mi
Registration #3	2008-10-15	38.430 mi
Registration #4	2009-08-24	46.098 mi
Registration #5	2010-12-22	51.122 mi
Registration #6	2011-12-05	55.553 mi
Registration #7	2012-11-28	60.595 mi
Registration #8	2014-04-24	71.193 mi
Registration #9	2014-04-25	71.209 mi
Registration #10	2015-06-09	79.340 mi
Registration #11	2015-07-06	79.708 mi
Registration #12	2015-07-06	79.708 mi
Registration #13	2015-07-06	79.708 mi
Registration #14	2015-07-06	79.708 mi
Registration #15	2015-07-06	79.708 mi
Registration #16	2015-07-06	79.708 mi
Registration #17	2015-07-06	79.708 mi
Registration #18	2015-07-06	79.708 mi
Registration #19	2015-07-06	79.708 mi
Registration #20	2015-07-06	79.708 mi
Registration #21	2015-07-06	79.708 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1705 mm
Length	4265 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1AZ1520846