



SH54EFO

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI (100BHP)
Colour	Silver
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg



**MOT history**

<b>MOT #16</b>	2020-11-03 15:51
<b>MOT test number</b>	109526022571
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-11-30
<b>Advice</b>	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

<b>MOT #15</b>	2020-11-03 11:34
<b>MOT test number</b>	759403914451
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Fail</b>	Nearside Rear Headlamp has a product on the light source which changes emitted colour to other than white or yellow (4.1.4 (b))
<b>Advice</b>	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Fail</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

<b>MOT #14</b>	2019-05-29 11:34
<b>MOT test number</b>	210066804610
<b>Result</b>	✓ Passed

**MOT #13** 2018-05-30 11:22**MOT test number** 276078553719**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Parkbrake lever has slight travel**MOT #12** 2018-05-30 11:22**MOT test number** 958578488897**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Parkbrake lever has slight travel**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #11** 2017-05-02 11:08**MOT test number** 987095485609**Result** ✓ Passed**Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #10** 2016-06-01 10:37**MOT test number** 182072708117**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Outer Body has slight corrosion sill (6.1.B.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Outer Body has slight corrosion sill (6.1.B.2)

**MOT #9** 2015-07-22 14:47**MOT test number** 436023305228**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Upper Ball joint has slight play (2.2.B.1f)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #8** 2014-07-09 16:53**MOT test number** 969860994147**Result** ✓ Passed**MOT #7** 2014-07-09 13:13**MOT test number** 867210394165**Result** ✗ Failed**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #6** 2013-07-20 12:19**MOT test number** 189161103239**Result** ✓ Passed**MOT #5** 2012-01-30 13:15**MOT test number** 919790832024**Result** ✓ Passed**Notice** Rear discs**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2011-01-31 15:43
MOT test number	799351331090
Result	✓ Passed
MOT #3	2009-11-27 12:07
MOT test number	314281539343
Result	✓ Passed
MOT #2	2008-11-28 15:36
MOT test number	522943238345
Result	✓ Passed
MOT #1	2007-11-09 12:10
MOT test number	342963217362
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SH54EFO</b>
Plate since	2019-06-29
Current registration	 <b>SH54EFO</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-12-01
Last registration	2020-11-03
Complete history	<a href="#">See info</a>



Registration #1	2004-12-01	26 mi
Registration #2	2007-11-09	95.026 mi
Registration #3	2008-11-28	110.225 mi
Registration #4	2009-11-27	119.564 mi
Registration #5	2011-01-31	125.475 mi
Registration #6	2012-01-30	131.295 mi
Registration #7	2013-07-20	142.669 mi
Registration #8	2014-07-09	147.070 mi
Registration #9	2014-07-09	147.070 mi
Registration #10	2015-05-20	151.377 mi
Registration #11	2015-05-20	151.377 mi
Registration #12	2015-05-20	151.377 mi
Registration #13	2015-05-20	151.377 mi
Registration #14	2015-05-20	151.377 mi
Registration #15	2015-05-20	151.377 mi
Registration #16	2015-05-20	151.377 mi
Registration #17	2015-05-20	151.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1462 mm
Length	4703 mm
Wheel base	2703 mm
Kerb weight	1566 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	AVB 257261