





report date: 2024-03-28

### General information

Make	MAZDA
Model	MX-5 SPORT NAV
Colour	Blue
Year of manufacture	2018
Top speed	133 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date	2021-09-13	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

## **MOT** history

MOT expiry date	2025-01-23
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #7	2024-01-24 16:32
MOT test number	674438238421
Result	<b>✓</b> Passed
Next expiry date	2025-01-23
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #6	2024-01-24 12:05
MOT test number	293717391912
Result	<b>X</b> Failed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excess (a) (i))	sive movement (5.3.4
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14)	1 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #5** 2023-11-15 11:39

MOT test number 813843083512

**Result** ✓ Passed

Advice Nearside Front Valve stem slightly damaged (5.2.3 (j))

Advice Tyre slightly damaged/cracking or perishing All four tyres perishing around outer bands (5.2.3 (d)

(ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge & n/s rear Unevenly worn (N/s rear central area) 205/45/17 (5.2.3 (e))

Advice Brake pad(s) wearing thin Fronts (1.1.13 (a) (ii))

MOT #4 2023-11-15 11:39

**MOT test number** 387411297064

Result X Failed

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge & n/s rear Unevenly worn (N/s rear central area) 205/45/17 (5.2.3 (e))

**Advice** Brake pad(s) wearing thin Fronts (1.1.13 (a) (ii))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))

**Advice** Tyre slightly damaged/cracking or perishing All four tyres perishing around outer bands (5.2.3 (d)

(ii))

MOT #3 2022-11-16 15:10

**MOT test number** 989930038135

**Result** 
✓ Passed

MOT #2 2021-11-17 15:32

MOT test number 615358660707

Result / Passed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

 MOT #1
 2021-05-11 09:17

 MOT test number
 947296717400

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	23 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	NIC
Plate since	
	Moro info

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-30
Last registration	2024-01-24
Complete history	See info



Registration #1	2018-04-30	18 mi
Registration #2	2021-05-11	11.798 mi
Registration #3		11.777 es
Registration #4	2021-11-17	12.438 mi
Registration #5	2022-11-16	21.536 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1735 mm
Height	1230 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1000 kg
Max. allowed weight	1260 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 31179492

CarCheck.co.uk page 12/12