



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V
Colour	Green
Year of manufacture	2004
Top speed	96 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-04
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-20
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	26
Total items failed	18

MOT #262023-11-21 17:08

MOT test number559051679056

Result✓ Passed

Next expiry date2024-11-20

MinorRegistration plate lamp insecure Near and Offside (4.7.1 (c) (i))

AdviceRear Integral body structure is corroded but structural rigidity is not significantly reduced ramp and frame structure HEAVILY CORRODED. (adapted vehicle) (6.1.1 (c) (i))

AdviceOffside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

AdvicePlay in steering rack inner joint(s) Near and Offside

AdviceFront Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Near and Offside heavily deteriorated (5.3.4 (a) (i))

**MOT #25**

2023-11-21 11:26

MOT test number

872904600141

Result**✗ Failed****Advice** Play in steering rack inner joint(s) Near and Offside**Fail** Rear Exhaust system insecure rear rubber broken (6.1.2 (a))**Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement Near and Offside heavily deteriorated (5.3.4 (a) (i))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**Minor** Registration plate lamp insecure Near and Offside (4.7.1 (c) (i))**Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced ramp and frame structure HEAVILY CORRODED. (adapted vehicle) (6.1.1 (c) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #24**

2022-11-10 16:41

MOT test number

336007745825

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened NEAR AND OFFSIDE (1.1.14 (a) (ii))**Advice** Passenger seat(s) missing at time of test**Advice** Front Coil spring corroded NEAR AND OFFSIDE (5.3.1 (b) (i))**MOT #23**

2022-11-10 16:38

MOT test number

370607392843

Result**✗ Failed****Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps NEAR AND OFFSIDE 501 bulb (4.7.1 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened NEAR AND OFFSIDE (1.1.14 (a) (ii))**Advice** Front Coil spring corroded NEAR AND OFFSIDE (5.3.1 (b) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps NEAR AND OFFSIDE (4.7.1 (b) (ii))**Advice** Passenger seat(s) missing at time of test

**MOT #22** 2021-10-22 16:22**MOT test number** 430976642858**Result** ✓ Passed**MOT #21** 2021-10-20 15:20**MOT test number** 500919256465**Result** ✗ Failed**Fail** Power steering component leaking switch area (2.1.5 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #20** 2020-10-29 16:25**MOT test number** 509212865255**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases at box (6.1.2 (a))**MOT #19** 2020-10-29 13:06**MOT test number** 257554055091**Result** ✗ Failed**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases at box (6.1.2 (a))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #18** 2019-10-24 09:39**MOT test number** 516994743051**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #17** 2019-10-24 09:39**MOT test number** 138734964034**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #16** 2018-11-14 17:22**MOT test number** 674638979249**Result** ✓ Passed**MOT #15** 2018-11-09 16:15**MOT test number** 633166106044**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Fail** Offside Rear Tyre has ply or cords exposed cracked (5.2.3 (d) (ii))**Fail** Power steering component leaking switch area (2.1.5 (a))**Fail** Exhaust system insecure (6.1.2 (a))**MOT #14** 2017-08-21 09:10**MOT test number** 119324241881**Result** ✓ Passed

**MOT #13** 2016-09-14 15:11**MOT test number** 921432131071**Result** ✓ Passed**MOT #12** 2016-09-14 10:17**MOT test number** 100001686075**Result** ✗ Failed

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #11 2016-05-05 11:03**MOT test number** 682791877184**Result** ✓ Passed**MOT #10** 2016-05-04 15:16**MOT test number** 576181567325**Result** ✗ Failed

Fail Fuel hose leaking filler neck (7.2.3)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt bottom ball joint (2.4.G.2)

MOT #9 2015-04-14 13:14**MOT test number** 597924005188**Result** ✓ Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #8 2014-03-27 10:46**MOT test number** 867846784031**Result** ✓ Passed

**MOT #7** 2013-04-16 11:16**MOT test number** 275856303182**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-04-12 14:39**MOT test number** 268343002147**Result** ✓ Passed**MOT #5** 2011-04-18 11:44**MOT test number** 289058601485**Result** ✓ Passed**MOT #4** 2010-04-15 11:56**MOT test number** 780045300182**Result** ✓ Passed**MOT #3** 2009-04-21 10:35**MOT test number** 302361619175**Result** ✓ Passed**MOT #2** 2008-04-15 09:29**MOT test number** 244486008103**Result** ✓ Passed**MOT #1** 2007-04-23 14:53**MOT test number** 353923617126**Result** ✓ Passed**Notice** Front windscreen damage in zone a but not a failure



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 November 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-12-06
Last registration	2023-11-21
Complete history	See info



Registration #1	2004-12-06	15 mi
Registration #2	2007-04-23	6.178 mi
Registration #3	2008-04-15	8.782 mi
Registration #4	2009-04-21	12.066 mi
Registration #5	2010-04-15	14.054 mi
Registration #6	2011-04-18	16.023 mi
Registration #7	2012-04-12	17.579 mi
Registration #8	2013-04-16	19.313 mi
Registration #9	2014-03-27	20.929 mi
Registration #10	2015-04-14	22.753 mi
Registration #11	2016-05-04	24.050 mi
Registration #12	2016-05-05	24.050 mi
Registration #13	2016-09-14	24.229 mi
Registration #14	2016-09-14	24.229 mi
Registration #15	2016-09-14	24.229 mi
Registration #16	2016-09-14	24.229 mi
Registration #17	2016-09-14	24.229 mi
Registration #18	2016-09-14	24.229 mi
Registration #19	2016-09-14	24.229 mi
Registration #20	2016-09-14	24.229 mi
Registration #21	2016-09-14	24.229 mi
Registration #22	2016-09-14	24.229 mi
Registration #23	2016-09-14	24.229 mi
Registration #24	2016-09-14	24.229 mi
Registration #25	2016-09-14	24.229 mi
Registration #26	2016-09-14	24.229 mi

Registration #27	2023-25-27	25,277-462
Registration #28	2023-25-28	25,277-462

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1035 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	F483509