





General information

| Make | PEUGEOT |
|---------------------|--------------------------|
| Model | EXPERT HDI 1000 L1H1 P/V |
| Colour | Red |
| Year of manufacture | 2013 |
| Top speed | 90 mph |
| 0 - 60 mph | 17.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |







Internet history

| Entry | 1 | | |
|-------|---|--|--|
| Date | | | |

2021-11-28

Listing price

Pictures

View report

17









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-12-07 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 11 |
| Total items failed | 16 |

| MOT #13 | | 2023-11-14 12:10 |
|---------------|--|--------------------------|
| MOT test | number | 213535218309 |
| Result | | 🗸 Passed |
| Next exp | iry date | 2024-12-07 |
| Minor | Nearside Front Outer Drive shaft joint constant velocity boot severely deter | iorated (6.1.7 (g) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or | light sources (4.7.1 (b) |

| MOT #12 | 2023-11-13 10:42 |
|--|----------------------|
| MOT test number | 799934689835 |
| Result | 🗙 Failed |
| Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriora | ted (6.1.7 (g) (i)) |
| Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Fail Offside Obligatory mirror missing (3.3 (a)) | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or ligh (i)) | t sources (4.7.1 (b) |
| Fail Central Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | |





| MOT #11 | 2022-12-08 12:42 | |
|--|-----------------------------|--|
| MOT test number | 604581028062 | |
| Result | ✓ Passed | |
| | | |
| MOT #10 | 2021-12-04 09:12 | |
| MOT test number | 131731929736 | |
| Result | ✓ Passed | |
| | | |
| MOT #9 | 2021-11-29 15:38 | |
| MOT test number | 689241734697 | |
| Result | 🗙 Failed | |
| Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no los of dirt (6.1.7 (g) (ii)) | nger prevents the ingress | |
| Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | | |
| Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) | | |
| Fail Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii)) | | |
| Fail Brake pedal anti-slip provision missing (1.1.2 (c)) | | |
| Fail Nearside Headlamp aim not tested (4.1.2 (b)) | | |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps (i)) | or light sources (4.7.1 (b) | |

| MOT #8 | 2021-01-08 14:52 |
|-----------------|------------------|
| MOT test number | 988319269171 |
| Result | ✓ Passed |





| MOT # | 7 | 2021-01-07 12:17 |
|--------|---|------------------|
| MOT te | est number | 892647990330 |
| Result | | 🗙 Failed |
| Fail | Nearside Rear All direction indicators incorrect colour (4.4.3 (a)) | |
| Fail | Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii)) | |
| Fail | Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure | (5.2.3 (d) (ii)) |
| Fail | Offside Rear All direction indicators incorrect colour (4.4.3 (a)) | |
| Fail | Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advid | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| МОТ #6 | 2020-01-20 16:43 |
|-----------------|------------------|
| MOT test number | 527474876024 |
| Result | ✓ Passed |

| MOT #5 | 2020-01-17 16:56 |
|--|------------------|
| MOT test number | 466564616839 |
| Result | 🗙 Failed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #4 | 2019-01-14 10:47 |
|-----------------|------------------|
| MOT test number | 854587507764 |
| Result | ✓ Passed |
| | |

| МОТ #3 | 2018-01-12 12:26 |
|-----------------|------------------|
| MOT test number | 895577040829 |
| Result | ✓ Passed |





| MOT #2 | 2017-01-13 13:50 |
|--|------------------|
| MOT test number | 799690614340 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2016-01-14 10:13 |
| MOT test number | 390981965323 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| X Untaxed | ✓ MOT |
|----------------------------------|------------------------------------|
| Tax expired: 22 February 2024 | Expires: 7 December 2024 |
| Tax status | Expired at 22 February 2024 |
| Days left | 66 days too late |
| MOT expiry date | 7 December 2024 |
| Full MOT history | <u>See MOT history</u> |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.11.111 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | 7 |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 15 |
| First mileage registration | 2013-01-18 |
| Last registration | 2023-11-14 |
| Complete history | <u>See info</u> |



| Registration #1 | 2013-01-18 | 25 mi |
|------------------|------------|------------|
| Registration #2 | 2016-01-14 | 26.227 mi |
| Registration #3 | 2017-01-13 | 35.388 mi |
| Registration #4 | 2018-01-12 | 41.780 mi |
| Registration #5 | 2019-01-14 | 46.693 mi |
| Registration #6 | 2020-01-17 | 52.103 mi |
| Registration #7 | 2020-01-20 | 52.103 mi |
| Registration #8 | 2021-01-07 | 62.275 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 esi |
| Registration #14 | | 11.117 mi |
| Registration #15 | | 11.117 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 59% |
| Children | 86% |
| Pedestrian | 26% |
| Safety systems | 26% |
| Overall rating | 54% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|------------------------|
| Width | 2194 mm |
| Height | 1980 mm |
| Length | 4805 mm |
| Kerb weight | 1780 kg |
| Max. allowed weight | 2661 kg |
| Additional information | |
| Fuel tank capacity | 80 I |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number CarCheck.co.uk | JBDF0027679 page 13/13 |