





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|----------------|
| Model | CEED CRDI 1 |
| Colour | Red |
| Year of manufacture | 2013 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 2.750 rpm |
| Engine capacity | 1.396 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 68.9 mpg |
| CO2 emission | 109 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-21

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-08-10 |
|--------------------|------------|
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #10 | 2023-08-11 13:49 |
|--|------------------|
| MOT test number | 304424364657 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-10 |
| Advice Under-tray fitted obscuring view of some components | |
| Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e)) | |
| Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | (a) (ii)) |
| Minor Windscreen wiper blade defective (3.4 (b) (i)) | |

| MOT #9 | 2022-08-24 08:57 |
|--|------------------|
| MOT test number | 910987786922 |
| Result | ✓ Passed |
| Advice Offside Front door mirror cover missing | |

| MOT #8 | 2021-09-17 11:00 |
|-----------------|------------------|
| MOT test number | 983406297116 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2020-11-02 12:00

MOT test number 576616665963

MOT #6 2020-07-13 14:01

MOT test number 219433356523

Result ✓ Passed

MOT #5 2019-04-17 15:47

MOT test number 711242942811

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking around the tread and has worn on outer edge (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer edges and has fine cracking around the tread (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking around the tread (5.2.3 (d) (ii))

MOT #4 2018-04-26 15:45

MOT test number 342693569294

Result \(\sqrt{Passed} \)

MOT #3 2017-05-02 10:28

MOT test number 413442461201

Result ✓ Passed

MOT #2 2017-05-02 09:36

MOT test number 307933465875

Result X Failed

Fail Nearside Rear Seat belt retracting mechanism defective (5.2.5b)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2016-05-04 10:14
MOT test number 542915499781

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 2 |
| MOT expiry date | 10 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| Owner | history |
|-------|---------|

| , | | |
|---|------------------|---|
| For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report | | |
| | | |
| | | |
| *************************************** | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this KIA had different number plates. | | |
| Number of plates | | |
| Current registration | UK 312 312 | |
| Plate since | | |
| Current registration | NK NK | |
| Plate since | | |
| | More info | > |

page 9/12 CarCheck.co.uk



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-05-03 |
| Last registration | 2023-08-11 |
| Complete history | See info |



| Registration #1 | 2013-05-03 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-05-04 | 40.178 mi |
| Registration #3 | 2017-05-02 | 46.762 mi |
| Registration #4 | 2017-05-02 | 46.762 mi |
| Registration #5 | 2018-04-26 | 54.399 mi |
| Registration #6 | 2019-04-17 | 62.682 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | n.m. |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 88% |
| Pedestrian | 61% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1780 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 4310 mm |
| Wheel base | 2650 mm |
| Kerb weight | 1489 kg |
| Max. allowed weight | 1910 kg |

Additional information

| Fuel tank capacity | 53 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2

Engine number D4FCDZ096042