



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-08-08
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-02-01
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	11

MOT #14	2023-01-17 17:15
MOT test number	595977552431
Result	✓ Passed
Next expiry date	2024-02-01

MOT #13	2022-01-31 15:00
MOT test number	426890699869
Result	✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #12	2022-01-31 15:00
MOT test number	735660590096
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #11**

2022-01-28 13:06

MOT test number

509018280191

Result**✗ Failed**

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Offside Rear Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
- Fail** Central Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Offside Rear Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #10

2021-02-02 16:45

MOT test number

176663609426

Result**✓ Passed**

- Advice** Prop shaft bearing has slight play (6.1.7 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

MOT #9

2021-02-02 10:23

MOT test number

327454345731

Result**✗ Failed**

- Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))
- Advice** Prop shaft bearing has slight play (6.1.7 (b) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #8** 2020-01-23 09:18**MOT test number** 843322838968**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-01-28 11:35**MOT test number** 965045158683**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Advise rear cooling pipe corroded and weeping fluid**MOT #6** 2018-01-16 15:44**MOT test number** 534124617250**Result** ✓ Passed**MOT #5** 2018-01-16 09:05**MOT test number** 282634352256**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2017-01-27 11:33**MOT test number** 903093276962**Result** ✓ Passed**MOT #3** 2016-01-29 08:53**MOT test number** 765156433075**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2015-01-19 09:01
MOT test number	758059415031
Result	✓ Passed

MOT #1	2014-01-31 16:13
MOT test number	938831634098
Result	✓ Passed

Notice

Oil leak



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✗
MOT

Expired:
1 February 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	1 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-29
Last registration	2023-01-17
Complete history	See info



Registration #1	2011-01-29	18 mi
Registration #2	2014-01-31	45.576 mi
Registration #3	2015-01-19	58.303 mi
Registration #4	2016-01-29	72.688 mi
Registration #5	2017-01-27	87.541 mi
Registration #6	2018-01-16	100.622 mi
Registration #7	2018-01-16	100.625 mi
Registration #8	2019-01-28	114.844 mi
Registration #9	2019-01-28	114.844 mi
Registration #10	2019-01-28	114.844 mi
Registration #11	2019-01-28	114.844 mi
Registration #12	2019-01-28	114.844 mi
Registration #13	2019-01-28	114.844 mi
Registration #14	2019-01-28	114.844 mi
Registration #15	2019-01-28	114.844 mi
Registration #16	2019-01-28	114.844 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBA731573