





report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-09-22

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-13
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	29
Total items failed	14

MOT #12	2023-09-05 09:38
MOT test number	939868661040
Result	✓ Passed
Next expiry date	2024-09-13
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #11	2023-09-04 09:43	
MOT test number	614577829722	
Result	X Failed	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))		
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		

MOT #10		2022-09-09 12:17
MOT test	number	751295365423
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



Result

BJ14PGU report date: 2024-03-28

✓ Passed

MOT #9 2022-09-08 09:01

MOT test number 663373781611

Result X Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8 2021-09-14 07:18

MOT test number 348039118865

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2020-08-12 13:31

MOT test number 627926952347

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Security of both outer cv boots

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/13



MOT #6 2020-08-12 08:41

MOT test number 429650616047

Result X Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Security of both outer cv boots

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2019-08-21 10:31

MOT test number 632186443638

Result ✓ Passed

MOT #4 2019-08-20 13:54

MOT test number 921070211155

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 5/13



MOT test number

Result

Advice Nearside Rear brake slightly binding

Advice Offside Rear brake slightly binding

MOT #2

MOT test number

611230471867

Result

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear brake slightly binding

Advice Nearside Rear brake slightly binding

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	13 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-29
Last registration	2023-09-05
Complete history	See info



Registration #1	2014-07-29	14 mi
Registration #2	2017-07-25	70.208 mi
Registration #3	2018-08-23	76.749 mi
Registration #4	2018-08-24	76.749 mi
Registration #5	2019-08-20	84.640 mi
Registration #6	2019-08-21	84.640 mi
Registration #7	2020-08-12	91.755 mi
Registration #8		11.777 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		91.077 mi
Registration #12		11.177 es
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	3/13

Number of axles 2

Engine number D292824