



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2021-11-29
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	27
Total items failed	16

MOT #17	2020-11-26 16:47
MOT test number	557623086484
Result	✓ Passed
Next expiry date	2021-11-29
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2020-11-24 09:43
MOT test number	428525575278
Result	✗ Failed
Pass with rectification	Windscreen washer not working (3.5 (a))
Fail	Brake lever has insufficient reserve travel (1.1.2 (a))
Pass with rectification	Nearside Windscreen wiper blade missing (3.4 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2019-11-28 16:47**MOT test number** 550650393510**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-11-27 13:23**MOT test number** 593309701520**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2018-11-23 15:52**MOT test number** 630335809908**Result** ✓ Passed**MOT #12** 2018-11-23 11:38**MOT test number** 107028690467**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2017-11-28 14:45**MOT test number** 937369991882**Result** ✓ Passed

**MOT #10**

2016-11-30 14:23

MOT test number

495229847338

Result

✓ Passed

Advice

Offside Front Tyre is worn smooth around inner and outer edges.

MOT #9

2016-11-30 09:43

MOT test number

694173519542

Result

✗ Failed

Fail

Rear Exhaust has a major leak of exhaust gases silencer. (7.1.2)

Fail

Offside Rear Tyre has ply or cords exposed around inner wall. (4.1.D.1b)

Advice

Offside Front Tyre is worn smooth around inner and outer edges.

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Fail

Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition rear silencer. (7.1.4)

Advice

Central Exhaust system is insecure and requires attention.

Fail

Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #8

2016-01-11 15:30

MOT test number

417807420669

Result

✓ Passed

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7** 2016-01-11 15:30**MOT test number** 605961168747**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-12-04 14:34**MOT test number** 569958534381**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Offside rear tyre perished**Notice** Front brakes binding**MOT #5** 2014-12-04 09:28**MOT test number** 416548434333**Result** ✗ Failed**Notice** Front brakes binding**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Offside rear tyre perished**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #4** 2013-12-04 10:58**MOT test number** 549568333372**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2012-10-31 14:25**MOT test number** 916015102326**Result** ✓ Passed**MOT #2** 2011-12-06 10:31**MOT test number** 357920641353**Result** ✓ Passed**MOT #1** 2011-12-06 09:52**MOT test number** 359720641348**Result** ✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
22 January 2021

✕
MOT

Expired:
29 November 2021

Tax status	Expired at 22 January 2021
Days left	1194 days too late
MOT expiry date	29 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PK58PLF
Plate since	2019-06-29
Current registration	 PK58PLF
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-31
Last registration	2020-11-26
Complete history	See info



Registration #1	2008-10-31	21 mi
Registration #2	2011-12-06	23.441 mi
Registration #3	2011-12-06	23.441 mi
Registration #4	2012-10-31	28.860 mi
Registration #5	2013-12-04	35.497 mi
Registration #6	2014-12-04	39.726 mi
Registration #7	2014-12-04	39.726 mi
Registration #8	2016-01-11	43.342 mi
Registration #9	2016-01-11	43.342 mi
Registration #10	2016-01-11	43.342 mi
Registration #11	2016-01-11	43.342 mi
Registration #12	2016-01-11	43.342 mi
Registration #13	2016-01-11	43.342 mi
Registration #14	2016-01-11	43.342 mi
Registration #15	2016-01-11	43.342 mi
Registration #16	2016-01-11	43.342 mi
Registration #17	2016-01-11	43.342 mi
Registration #18	2016-01-11	43.342 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141