



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO L2H1 2300 CDTI ECOFLEX S/S
Colour	Red
Year of manufacture	2016
Top speed	100 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-12-30
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	8

MOT #6	2023-06-06 14:35
MOT test number	754864597575
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn and lipped (1.1.14 (a) (ii))
Advice	Offside Front head lamp brackets broken loose
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn and lipped (1.1.14 (a) (ii))
Advice	Nearside Front head lamp bracket broken

**MOT #5**

2023-06-01 17:00

MOT test number

326996032761

Result**✗ Failed**

- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Rear Brake lever has insufficient reserve travel hand brake high (1.1.2 (a))
- Fail** Nearside Rear Position lamp showing white light to the rear light lens missing (4.2.3 (a) (ii))
- Advice** Offside Front head lamp brackets broken loose
- Fail** Nearside Rear Body component damaged and likely to cause injury light lens smashed missing sharp edges (6.2.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened worn and lipped (1.1.14 (a) (ii))
- Fail** Nearside Rear Road wheel badly distorted rim bent outer (5.2.2 (c) (i))
- Fail** Nearside Rear Stop lamp(s) emits other than a steady red light lens missing (4.3.3 (a) (ii))
- Advice** Nearside Front head lamp bracket broken
- Fail** Nearside Rear Position lamp lens seriously defective (4.2.1 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened worn and lipped (1.1.14 (a) (ii))

MOT #4

2022-05-30 13:46

MOT test number

981450161292

Result**✓ Passed****MOT #3**

2021-08-21 09:41

MOT test number

310783551791

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2020-09-15 09:32
MOT test number	840205446201
Result	✓ Passed

MOT #1	2019-10-11 09:12
MOT test number	640812573367
Result	✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

X

Untaxed

Tax expired:
8 November 2023

✓

MOT

Expires:
5 June 2024

Tax status	Expired at 8 November 2023
Days left	173 days too late
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 EY66KHE
Plate since	2019-06-29
Current registration	 EY66KHE
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-31
Last registration	2023-06-06
Complete history	See info



Registration #1	2016-10-31	15 mi
Registration #2	2019-10-11	26.471 mi
Registration #3	2020-09-15	31.952 mi
Registration #4	2021-08-21	41.254 mi
Registration #5	2022-06-06	51.557 mi
Registration #6	2023-06-06	61.860 mi
Registration #7	2024-03-28	72.163 mi
Registration #8	2024-03-28	82.466 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1385 kg
Max. allowed weight	2385 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	330A10006267248 LN9