



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Blue
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 4

Date	2022-01-06
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 3

Date	2022-01-06
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

Entry 2

Date	2021-08-19
Pictures	1
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-08-17
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-01-17
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #8	2024-01-04 17:10
MOT test number	291555091371
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #7	2024-01-04 08:48
MOT test number	923696955240
Result	✗ Failed
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6** 2023-01-18 14:33**MOT test number** 796692500345**Result** ✓ Passed**Advice** Front Inner Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Inner Brake pad(s) wearing thin worn close to limit (1.1.13 (a) (ii))**MOT #5** 2022-01-12 15:46**MOT test number** 989161762704**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2021-02-10 15:31**MOT test number** 881911642354**Result** ✓ Passed**MOT #3** 2021-02-10 10:11**MOT test number** 546878811361**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2020-02-03 09:26**MOT test number** 213616331404**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #1	2020-02-03 09:26
MOT test number	217718091093
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
17 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	17 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KE66YVF
Plate since	2019-09-28
Current registration	KE66YVF
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2017-02-15
Last registration	2024-01-04
Complete history	See info



Registration #1	2017-02-15	8 mi
Registration #2	2020-02-03	57.404 mi
Registration #3	2020-02-03	57.404 mi
Registration #4	2021-02-10	72.246 mi
Registration #5	2021-02-10	72.247 mi
Registration #6	2022-02-03	72.247 mi
Registration #7	2022-02-03	72.247 mi
Registration #8	2022-02-03	72.247 mi
Registration #9	2022-02-03	72.247 mi
Registration #10	2022-02-03	72.247 mi
Registration #11	2022-02-03	72.247 mi
Registration #12	2022-02-03	72.247 mi
Registration #13	2022-02-03	72.247 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1617 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	2043168
---------------	---------