



report date: 2024-03-29

General information

Make	NISSAN
Model	TERRANO TD SE
Colour	Blue
Year of manufacture	2004
Top speed	106 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	304 Nm at 1.600 rpm
Engine capacity	2.953 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	240 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-08-31
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-06-16
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	48
Total items failed	13

MOT #22 2021-06-17 15:09

MOT test number 390208940012

Result ✓ Passed

Next expiry date 2022-06-16

Advice Fuel Pipe/s corroded FRONT TO REAR

Advice Front UNDER BODY AND FRONT & REAR SUSPENSION VERY RUSTY.

Advice Fuel Pipe/s corroded FRONT TO REAR

MOT #21 2021-06-05 16:46

MOT test number 956543114565

Result ✗ Failed

Advice Fuel Pipe/s corroded FRONT TO REAR

Fail Nearside Windscreen wiper blade missing (3.4 (b) (ii))

Advice Fuel Pipe/s corroded FRONT TO REAR

Fail Nearside Front Brake lining(s) missing WORN DOWN TO BARE METAL (1.1.13 (c))

Advice Front UNDER BODY AND FRONT & REAR SUSPENSION VERY RUSTY.

**MOT #20** 2020-05-23 16:07**MOT test number** 345900895579**Result** ✓ Passed**Advice** Under body very rusty**MOT #19** 2019-05-14 09:24**MOT test number** 782957637565**Result** ✓ Passed**Advice** Front Oil leak, but not excessive ENGINE SUMP (8.4.1 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Fuel Pipe/s corroded FRONT TO REAR**MOT #18** 2018-05-03 16:33**MOT test number** 539724928838**Result** ✓ Passed**Advice** Vehicle structure has slight corrosion UNDER BODY / FRONT AND REAR SUSPENSION (6.1.A.1)**Advice** Offside Rear Fuel pipe slightly chafed FUEL PIPES AT REAR DAMP (7.2.2)**MOT #17** 2018-05-02 18:30**MOT test number** 208443287622**Result** ✗ Failed**Advice** Offside Rear Fuel pipe slightly chafed FUEL PIPES AT REAR DAMP (7.2.2)**Advice** Vehicle structure has slight corrosion UNDER BODY / FRONT AND REAR SUSPENSION (6.1.A.1)**Fail** Offside Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

**MOT #16** 2017-05-12 17:53**MOT test number** 151571895251**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #15** 2017-05-10 14:51**MOT test number** 709554467287**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Brake pipe inadequately supported (3.6.B.1)**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Fail** Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Offside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #14** 2015-04-21 12:08**MOT test number** 147851415198**Result** ✓ Passed**MOT #13** 2015-04-21 12:08**MOT test number** 797831815184**Result** ✗ Failed**Pass with rectification** Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #12	2015-04-03 17:27
MOT test number	289362295059
Result	✗ Failed
Fail	Offside Front Front constant velocity joint is excessively worn (2.5.C.1b)

MOT #11	2014-03-18 15:05
MOT test number	896537074021
Result	✓ Passed
Advice	Front Drag link end ball joint has slight play (2.2.B.1f)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Front wheel bearing has slight play (2.5.A.3c)
Notice	UNDER BODY AND SUSPENSION VERY DRY AND RUSTY'
Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)

MOT #10	2014-03-17 10:38
MOT test number	578944074053
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Front wheel bearing has slight play (2.5.A.3c)
Notice	UNDER BODY AND SUSPENSION VERY DRY AND RUSTY'
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)
Advice	Front Drag link end ball joint has slight play (2.2.B.1f)

**MOT #9**

2013-03-21 13:37

MOT test number

606450983069

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Fuel pipe/s corroded
- Notice** O/s/f and n/s/f slight play on wheels
- Advice** Centre Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #8

2013-03-12 14:23

MOT test number

605811573080

Result

✗ Failed

- Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Centre Brake pipe slightly corroded (3.6.B.2c)
- Notice** Fuel pipe/s corroded
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/f and n/s/f slight play on wheels

MOT #7

2012-03-14 13:08

MOT test number

206864972004

Result

✓ Passed

- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #6** 2011-03-14 11:42**MOT test number** 216913271008**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-03-18 12:12**MOT test number** 470557370040**Result** ✓ Passed**MOT #4** 2010-03-15 12:08**MOT test number** 930734870043**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2009-03-19 15:47**MOT test number** 133038279071**Result** ✓ Passed**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-02-05 11:03**MOT test number** 632396138072**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)



MOT #1	2007-02-12 09:18
MOT test number	534753147027
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-01
Last registration	2021-06-17
Complete history	See info



Registration #1	2004-03-01	17 mi
Registration #2	2007-02-12	14.105 mi
Registration #3	2008-02-05	17.553 mi
Registration #4	2009-03-19	29.058 mi
Registration #5	2010-03-15	39.983 mi
Registration #6	2010-03-18	40.055 mi
Registration #7	2011-03-14	51.322 mi
Registration #8	2012-03-14	63.179 mi
Registration #9	2013-03-12	72.676 mi
Registration #10	2013-03-21	72.678 mi
Registration #11	2014-03-17	72.693 mi
Registration #12	2015-03-20	72.707 mi
Registration #13	2016-03-20	72.721 mi
Registration #14	2017-03-20	72.735 mi
Registration #15	2018-03-20	72.749 mi
Registration #16	2019-03-20	72.763 mi
Registration #17	2020-03-20	72.777 mi
Registration #18	2021-03-20	72.791 mi
Registration #19	2022-03-20	72.805 mi
Registration #20	2023-03-20	72.819 mi
Registration #21	2024-03-20	72.833 mi
Registration #22	2025-03-20	72.847 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1755 mm
Height	1810 mm
Length	4722 mm
Wheel base	2650 mm
Kerb weight	1878 kg
Max. allowed weight	2580 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

163489