



General information

Make	MINI
Model	PACEMAN COOPER SD
Colour	White
Year of manufacture	2015
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-10-02
Pictures	1
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-10-01
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #8	2024-02-01 14:27
MOT test number	722626743397
Result	✓ Passed
Next expiry date	2025-02-02

MOT #7	2024-01-31 13:38
MOT test number	935444244775
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #6	2023-02-03 10:34
MOT test number	417986561436
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened Front And Rear (1.1.14 (a) (ii))

MOT #5	2021-11-24 16:43
MOT test number	565602715359
Result	✓ Passed

**MOT #4**

2021-11-23 10:40

**MOT test number**

349577541094

**Result****✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge nail in tyre TPMS light on (5.2.3 (e))**Fail** Offside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**MOT #3**

2020-10-30 15:20

**MOT test number**

446057187262

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2019-10-31 14:41

**MOT test number**

695033968795

**Result****✓ Passed****Advice** Rear Tyre slightly damaged/cracking or perishing slight cracking (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1**

2018-10-25 12:51

**MOT test number**

473953459258

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
2 February 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	2 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-30
Last registration	2024-02-01
Complete history	<a href="#">See info</a>



Registration #1	2015-01-30	12 mi
Registration #2	2018-10-25	24.738 mi
Registration #3	2019-10-31	29.847 mi
Registration #4	2020-10-30	33.484 mi
Registration #5	2020-10-30	33.484 mi
Registration #6	2020-10-30	33.484 mi
Registration #7	2020-10-30	33.484 mi
Registration #8	2020-10-30	33.484 mi
Registration #9	2020-10-30	33.484 mi
Registration #10	2020-10-30	33.484 mi
Registration #11	2020-10-30	33.484 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

54569168