



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	239 g/km
CO2 label	L





## Internet history

### Entry 3

Date 2022-03-12

Pictures 7

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date 2021-11-03

Pictures 7

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date 2021-02-06

Pictures 1

Listing price [View report](#)



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	48
Total items failed	8

MOT #17	2023-10-03 10:43
MOT test number	911351922465
Result	✓ Passed
Next expiry date	2024-10-23
Advice	Parking brake performance poor
Advice	Offside Front Slight play in inner track rod
Advice	Nearside Front Very slight play in inner track rod
Advice	Offside Front Anti-roll bar link worn

MOT #16	2022-09-26 15:01
MOT test number	149566866920
Result	✓ Passed
Advice	Front Head lamp beam patterns slightly poor
Advice	Front Brake discs worn
Advice	Rear Brake discs worn
Advice	Front Inner Brake pads worn to limit
Advice	Nearside Rear Inner Brake pad worn

**MOT #15**

2022-09-26 15:01

**MOT test number**

326809805511

**Result****✗ Failed****Advice** Nearside Rear Inner Brake pad worn**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Head lamp beam patterns slightly poor**Advice** Front Brake discs worn**Advice** Rear Brake discs worn**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Inner Brake pads worn to limit**MOT #14**

2021-10-04 13:04

**MOT test number**

201526385145

**Result****✓ Passed****Advice** Nearside Steering rack gaiter deteriorated**Advice** Parking brake performance poor**Advice** Nearside Front Slight play in anti-roll bar link**MOT #13**

2020-10-19 16:18

**MOT test number**

241185920653

**Result****✓ Passed****Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2019-04-24 14:23**MOT test number** 396008920199**Result** ✓ Passed**MOT #11** 2019-04-23 14:28**MOT test number** 654955865162**Result** ✗ Failed**Advice** Front Fog lights not working**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Engine cover fitted / Under vehicle cover fitted (engine/gearbox)**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Tyre starting to wear on outside edge**Advice** Smoke test carried out, no reading detected by smoke meter 0.00, therefore default reading 3.50m-1 reached**MOT #10** 2018-03-15 13:36**MOT test number** 529907515078**Result** ✓ Passed**Advice** Both front tyres worn on outer edge**MOT #9** 2015-05-01 16:21**MOT test number** 596481325139**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2014-03-27 14:58**MOT test number** 585736384081**Result** ✓ Passed**Advice** Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**Notice** Front antiroll bar slightly misaligned**MOT #7** 2014-03-25 16:55**MOT test number** 175084584499**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Advice** Offside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**Notice** Front antiroll bar slightly misaligned**Advice** Nearside Front position lamp(s) deteriorated, but still visible from a reasonable distance (1.1.A.3d)**MOT #6** 2013-03-28 12:28**MOT test number** 897197483051**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

**MOT #5** 2013-03-28 12:28**MOT test number** 448527383046**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2012-03-29 16:00**MOT test number** 108149782024**Result** ✓ Passed**MOT #3** 2011-03-18 14:12**MOT test number** 325437771023**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear discs corroded but not restricting brake performance**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-03-18 14:12**MOT test number** 709237971032**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear discs corroded but not restricting brake performance**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-03-25 12:33
MOT test number	132724680032
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
23 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	23 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 HV07HKK
Plate since	2024-03-29
Current registration	 HV07HKK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-29
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2007-03-29	25 mi
Registration #2	2010-03-25	42.988 mi
Registration #3	2011-03-18	59.256 mi
Registration #4	2012-03-29	76.150 mi
Registration #5	2013-03-28	91.594 mi
Registration #6	2014-03-25	110.367 mi
Registration #7	2014-03-27	110.471 mi
Registration #8	2015-05-01	125.070 mi
Registration #9	2018-03-15	150.945 mi
Registration #10	2019-04-23	161.632 mi
Registration #11	2020-05-20	171.377 mi
Registration #12	2021-05-20	181.377 mi
Registration #13	2022-05-20	191.377 mi
Registration #14	2023-05-20	201.377 mi
Registration #15	2024-05-20	211.377 mi
Registration #16	2025-05-20	221.377 mi
Registration #17	2026-05-20	231.377 mi
Registration #18	2027-05-20	241.377 mi
Registration #19	2028-05-20	251.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2133 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	480157