



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI T3
Colour	Silver
Year of manufacture	2006
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-31
Pictures	2
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-10
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	45
Total items failed	2

MOT #20	2024-03-11 17:49
---------	------------------

MOT test number	742140031585
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-10
------------------	------------

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19**

2024-03-11 16:16

MOT test number

901629173213

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #18

2023-03-01 10:42

MOT test number

197832002091

Result**✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test

MOT #17

2022-07-18 13:29

MOT test number

691641760789

Result**✓ Passed**

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16** 2022-07-18 09:21**MOT test number** 842095856184**Result** ✗ Failed**MAJOR** Nearside Windscreen wiper blade missing (3.4 (b) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Front Windscreen washer not working (3.5 (a))**MAJOR** Offside Front Windscreen wiper missing (3.4 (a))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #15** 2021-07-07 08:21**MOT test number** 279315368428**Result** ✓ Passed**MOT #14** 2020-07-21 11:24**MOT test number** 933561811757**Result** ✓ Passed**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #13** 2019-07-02 09:39**MOT test number** 645231058592**Result** ✓ Passed**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12** 2018-06-26 11:00**MOT test number** 375586701938**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2017-06-21 09:53**MOT test number** 622793356306**Result** ✓ Passed**MOT #10** 2017-06-21 09:53**MOT test number** 454610410984**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #9** 2016-07-19 09:02**MOT test number** 483026061550**Result** ✓ Passed**MOT #8** 2015-06-25 11:23**MOT test number** 505006475110**Result** ✓ Passed**Notice** O/s/r tyre has splits all round outside tread but no cords are visible**MOT #7** 2014-06-27 12:32**MOT test number** 196738874188**Result** ✓ Passed**Notice** Both rear tyres are slightly perished and wearing uneven on the inner edge

**MOT #6** 2013-07-18 08:47**MOT test number** 217149693169**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-06-28 10:44**MOT test number** 799480082126**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre wearing uneven on the inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-06-28 09:25**MOT test number** 539240182170**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.D.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside rear tyre wearing uneven on the inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-07-14 09:44**MOT test number** 536085691119**Result** ✓ Passed**Notice** Both rear tyres wearing uneven in tread pattern



MOT #2	2010-07-26 10:16
MOT test number	771637300246
Result	✓ Passed

MOT #1	2009-09-07 13:27
MOT test number	741200059288
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 March 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-07-19
Last registration	2024-03-11
Complete history	See info



Registration #1	2006-07-19	8 mi
Registration #2	2009-09-07	15.221 mi
Registration #3	2010-07-26	19.551 mi
Registration #4	2011-07-14	20.500 mi
Registration #5	2012-06-28	21.258 mi
Registration #6	2012-06-28	21.267 mi
Registration #7	2013-07-18	21.995 mi
Registration #8	2014-06-27	22.689 mi
Registration #9	2015-06-25	22.907 mi
Registration #10	2016-07-19	23.168 mi
Registration #11	2017-06-21	23.387 mi
Registration #12	2018-06-21	23.377 mi
Registration #13	2019-06-21	23.377 mi
Registration #14	2020-06-21	23.377 mi
Registration #15	2021-06-21	23.377 mi
Registration #16	2022-06-21	23.377 mi
Registration #17	2023-06-21	23.377 mi
Registration #18	2024-03-11	23.377 mi
Registration #19	2024-03-11	23.377 mi
Registration #20	2024-03-11	23.377 mi
Registration #21	2024-03-11	23.377 mi
Registration #22	2024-03-11	23.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1250 kg
Max. allowed weight	1670 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3ZZU805903