





report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SE
Colour	Black
Year of manufacture	2008
Top speed	117 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-11

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

Minor

MOT expiry date	2024-04-28
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	9

MOT #17	2024-04-27 16:49
MOT test number	950314078562
Result	✓ Passed
Next expiry date	2025-04-28

MOT #16	2023-04-20 12:58
MOT test number	153418963565
Result	√ Passed

MOT #15	2022-04-23 12:25
MOT test number	116434112498
Result	✓ Passed
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14		2022-04-23 12:25
MOT test number		551156476147
Result		X Failed
Dage with restification	Nearside Front Headlann aim too high (4.1.2 (a))	

Pass with rectificationNearside Front Headlamp aim too high (4.1.2 (a))MinorNearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))MinorFront Windscreen wiper blade defective (3.4 (b) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2021-04-16 15:16

MOT test number 216745723881

MOT #12 2021-04-16 08:45

MOT test number 899090541975

Result X Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11 2020-04-29 14:51

MOT test number 656452570066

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2019-03-11 17:53

MOT test number 640030814738

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2019-03-11 17:53

MOT test number 663139018029

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Undertray insecure (8.1.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Pass with rectification Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8 2018-03-16 20:35

MOT test number 647984193485

Result ✓ Passed

MOT #7 2017-09-22 11:09

MOT test number 325408574617

Result ✓ Passed

MOT #6 2016-04-18 13:32

MOT test number 637666812960

Advice Tyre worn close to the legal limit Both rear 2mm (4.1.E.1)

Advice Tyre worn close to the legal limit Both front inner edges (4.1.E.1)

Advice Nearside Front Front drive shaft coupling flexible rubber or fabric coupling unit slightly cracked

(2.5.C.1d)

MOT #5 2014-12-05 12:45

MOT test number 585339634338

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2013-11-21 13:47
--------	------------------

MOT test number 356275523310

Result
✓ Passed

MOT #3 2012-11-15 15:07

MOT test number 379540922355

Result

Passed

MOT #2 2011-11-09 15:01

MOT test number 296363711387

Result
✓ Passed

MOT #1 2011-11-09 11:32

MOT test number 756843011306

Result X Failed

Pass with rectification Centre Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Fail Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-21
Last registration	2024-04-27
Complete history	See info



Registration #1	2008-11-21	25 mi
Registration #2	2011-11-09	65.390 mi
Registration #3	2011-11-09	65.403 mi
Registration #4	2012-11-15	72.228 mi
Registration #5	2013-11-21	83.627 mi
Registration #6	2014-12-05	87.592 mi
Registration #7	2016-04-18	90.905 mi
Registration #8	2017-09-22	98.157 mi
Registration #9	2018-03-16	99.400 mi
Registration #10	2019-03-11	105.163 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1295 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	13/13