




report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 T5 INSCRIPTION PRO AWD
Colour	Grey
Year of manufacture	2018
Top speed	137 mph
0 - 60 mph	6.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	251 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history



Entry 5

Date	2023-02-13
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 4


Date	2023-01-26
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 3

Date	2023-01-25
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2021-11-29
Pictures	0
Listing price	View report

source: heycar.co.uk


Entry 1

CarCheck.co.uk

Date	2021-11-05
------	------------

Pictures	35
----------	----

Listing price	View report
---------------	-----------------------------



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #4	2023-10-24 15:51
MOT test number	243152129410
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2023-10-24 12:30
MOT test number	179277454220
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn low in tread. (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Nearside Rear Outer Tyre has a lump, caused by separation or partial failure of its structure Tyre has small lump on the outer sidewall. (5.2.3 (d) (ii))

MOT #2	2022-10-25 12:40
MOT test number	200588243240
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Within tread pattern (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Within tread pattern (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #1	2021-10-04 08:50
MOT test number	556626299567
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-10-26
Last registration	2023-10-24
Complete history	See info



Registration #1	2018-10-26	25 mi
Registration #2	2021-10-04	23.700 mi
Registration #3	2019-10-26	25.277 mi
Registration #4	2019-10-26	25.277 mi
Registration #5	2022-10-25	30.716 mi
Registration #6	2019-10-26	25.277 mi
Registration #7	2019-10-26	25.277 mi
Registration #8	2019-10-26	25.277 mi
Registration #9	2019-10-26	25.277 mi
Registration #10	2019-10-26	25.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1773 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2504136