



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Black
Year of manufacture	2008
Top speed	140 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	221 g/km
CO2 label	K





Internet history

Entry 2



Date	2023-01-20
Pictures	20
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-08-26
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	23
Total items failed	7

MOT #20	2024-01-18 12:52
MOT test number	724041743343
Result	✓ Passed
Next expiry date	2025-01-23
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2023-01-24 11:27
MOT test number	383914078027
Result	✓ Passed

MOT #18	2022-10-10 12:00
MOT test number	966082532935
Result	✓ Passed

MOT #17	2021-10-28 15:16
MOT test number	602953571909
Result	✓ Passed

**MOT #16** 2021-10-28 14:08**MOT test number** 428596637400**Result** ✗ Failed**Fail** Rear Registration plate incorrect (0.1 (c))**MOT #15** 2021-08-26 13:08**MOT test number** 208824506786**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #14** 2020-10-09 15:26**MOT test number** 139107142130**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play rear arm (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play rear arm (5.3.4 (a) (i))**MOT #13** 2019-10-10 13:29**MOT test number** 791085799513**Result** ✓ Passed**MOT #12** 2018-10-09 12:59**MOT test number** 299510773568**Result** ✓ Passed**MOT #11** 2018-10-08 10:42**MOT test number** 628969342513**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2017-11-10 12:35**MOT test number** 509669448830**Result** ✓ Passed**Advice** Rear exhaust mounting broken away from pipe**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2016-10-28 08:20**MOT test number** 778318205702**Result** ✓ Passed**MOT #8** 2015-11-20 11:37**MOT test number** 543252292189**Result** ✓ Passed**MOT #7** 2015-11-18 16:04**MOT test number** 670553964487**Result** ✗ Failed**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #6** 2015-04-17 10:57**MOT test number** 526957205179**Result** ✓ Passed

**MOT #5** 2014-04-22 10:41**MOT test number** 729022714147**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Nearside and offside front tyres treads cracking and wear to inner edges**MOT #4** 2013-05-20 16:54**MOT test number** 907200943183**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-05-08 13:57**MOT test number** 197249822178**Result** ✓ Passed**Notice** Rear brake discs are slightly worn**Notice** Front brake discs are slightly worn**MOT #2** 2011-04-11 15:25**MOT test number** 109201501120**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12011-04-11 09:12

MOT test number488061001152

ResultX Failed

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
23 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-05-09
Last registration	2024-01-18
Complete history	See info



Registration #1	2008-05-09	25 mi
Registration #2	2011-04-11	28.892 mi
Registration #3	2011-04-11	28.914 mi
Registration #4	2012-05-08	45.283 mi
Registration #5	2013-05-20	47.890 mi
Registration #6	2014-04-22	53.223 mi
Registration #7	2015-04-17	60.239 mi
Registration #8	2015-11-18	60.953 mi
Registration #9	2015-11-20	60.954 mi
Registration #10	2016-10-28	66.694 mi
Registration #11	2017-11-10	72.215 mi
Registration #12	2018-10-08	74.608 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi
Registration #21	2019-05-20	75.277 mi
Registration #22	2019-05-20	75.277 mi
Registration #23	2019-05-20	75.277 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430986681