



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA LX
Colour	Grey
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT #21 2022-09-07 15:41

MOT test number 703761441555

Result ✓ Passed

Next expiry date 2023-09-06

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #20**

2022-09-06 12:26

**MOT test number**

299640684419

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))
- Fail** Offside Front Direction indicator light intensity significantly reduced (4.4.3 (a))

**MOT #19**

2021-09-07 11:23

**MOT test number**

143600694496

**Result****✓ Passed**

- Advice** Rear exhaust corroded

**MOT #18**

2021-03-31 14:32

**MOT test number**

753572170793

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #17**

2021-03-18 12:31

**MOT test number**

243500383909

**Result**

✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #16** 2020-02-19 09:41**MOT test number** 522874579223**Result** ✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15** 2019-03-01 12:11**MOT test number** 404771258680**Result** ✓ Passed

- Advice** Nearside Rear tyre perishing
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear tyre perishing
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both wearing (1.1.14 (a) (ii))

**MOT #14** 2018-02-19 11:37**MOT test number** 642626442695**Result** ✓ Passed**MOT #13** 2018-02-19 11:31**MOT test number** 244889063020**Result** ✗ Failed

- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Rear Exhaust has a major leak of exhaust gases Rear silencer clamp rusted through (7.1.2)

**MOT #12** 2017-02-13 11:33**MOT test number** 330441208421**Result** ✓ Passed

**MOT #11** 2016-02-02 09:35**MOT test number** 139947876570**Result** ✓ Passed**MOT #10** 2015-02-06 11:21**MOT test number** 896357135016**Result** ✓ Passed**MOT #9** 2013-11-07 14:33**MOT test number** 646501113397**Result** ✓ Passed**MOT #8** 2012-10-29 10:48**MOT test number** 575523602371**Result** ✓ Passed**MOT #7** 2012-10-29 10:48**MOT test number** 8937703602348**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #6** 2011-11-08 12:07**MOT test number** 105492011346**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2011-11-08 12:07**MOT test number** 496812611312**Result** ✗ Failed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-11-10 14:46**MOT test number** 421334710425**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2009-09-16 14:52**MOT test number** 424669359293**Result** ✓ Passed**MOT #2** 2008-09-10 16:31**MOT test number** 370264858492**Result** ✓ Passed**MOT #1** 2007-09-11 12:17**MOT test number** 974054957248**Result** ✓ Passed**Notice** Nsf tyre starting to wear inner edge . â€ â€ â€ osf tyre worn inner edge





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-09-23
Last registration	2022-09-07
Complete history	<a href="#">See info</a>



Registration #1	2004-09-23	11 mi
Registration #2	2007-09-11	17.623 mi
Registration #3	2008-09-10	23.808 mi
Registration #4	2009-09-16	30.364 mi
Registration #5	2010-11-10	41.092 mi
Registration #6	2011-11-08	45.887 mi
Registration #7	2012-10-29	47.244 mi
Registration #8	2013-11-07	47.933 mi
Registration #9	2015-02-06	48.694 mi
Registration #10	2016-02-02	49.085 mi
Registration #11	2017-02-13	49.369 mi
Registration #12	2018-05-20	50.000 mi
Registration #13	2019-05-20	50.000 mi
Registration #14	2020-05-20	50.000 mi
Registration #15	2021-05-20	50.000 mi
Registration #16	2022-05-20	50.000 mi
Registration #17	2023-05-20	50.000 mi
Registration #18	2024-05-20	50.000 mi
Registration #19	2025-05-20	50.000 mi
Registration #20	2026-05-20	50.000 mi
Registration #21	2027-05-20	50.000 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1975 mm
Height	1401 mm
Length	4167 mm
Wheel base	2540 mm
Kerb weight	1166 kg
Max. allowed weight	1666 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FSR94907419