



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER S
Colour	Orange
Year of manufacture	2011
Top speed	142 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	136 g/km
CO2 label	E





MOT history

MOT expiry date	2024-07-02
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	4

MOT #11 2023-07-03 16:33

MOT test number 663970767665

Result ✓ Passed

Next expiry date 2024-07-02

Advice Offside Rear Tyre worn close to legal limit/worn on edge and perishing (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10 2022-06-29 09:38

MOT test number 406283325496

Result ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Stepping on offside rear tyre

MOT #9 2021-06-24 09:48

MOT test number 558404967387

Result ✓ Passed

MOT #8 2020-06-17 12:35

MOT test number 769247453753

Result ✓ Passed

**MOT #7** 2019-02-23 15:55**MOT test number** 595085635213**Result** ✓ Passed**MOT #6** 2018-02-22 12:12**MOT test number** 699447195684**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2018-02-21 16:35**MOT test number** 720173357922**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-02-14 11:54**MOT test number** 159900265872**Result** ✓ Passed**MOT #3** 2017-02-14 11:54**MOT test number** 264766754302**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working x2 (1.1.C.1d)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #2	2016-02-01 15:03
MOT test number	481091206254
Result	✓ Passed
MOT #1	2015-01-23 17:12
MOT test number	995053225095
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
2 July 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	2 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-12-22
Last registration	2023-07-03
Complete history	See info



Registration #1	2011-12-22	27 mi
Registration #2	2015-01-23	23.412 mi
Registration #3	2016-02-01	33.876 mi
Registration #4	2017-02-14	48.434 mi
Registration #5	2017-02-14	48.434 mi
Registration #6	2018-02-21	58.554 mi
Registration #7	2019-05-29	59.277 mi
Registration #8	2019-05-29	59.277 mi
Registration #9	2019-05-29	59.277 mi
Registration #10	2019-05-29	59.277 mi
Registration #11	2019-05-29	59.277 mi
Registration #12	2023-07-03	59.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	A668J122