





report date: 2024-03-28

General information

Make	ТОУОТА
Model	COROLLA VERSO VVTI T3
Colour	Grey
Year of manufacture	2006
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2022-03-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



WV56NUA report date: 2024-03-28

MOT history

MOT expiry date	2025-03-06
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	8
Total items failed	12

MOT #20	2024-03-07 12:04
MOT test number	584420838279
Result	✓ Passed
Next expiry date	2025-03-06
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

MOT #19	2023-03-02 15:43
MOT test number	535868563713
Result	✓ Passed

MOT #	18	2023-03-02 14:34
MOT te	st number	855602767477
Result		× Failed
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #17	2022-03-02 11:34
MOT test number	767192159678
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #16 2021-09-29 08:01

MOT test number 116709490207

Result \rightarrow Passed

MOT #15 2020-12-14 11:16

MOT test number 205868827651

Result ✓ Passed

MOT #14 2020-12-14 11:16

MOT test number 762928153270

Result X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13 2019-12-17 14:44

MOT test number 147951710535

Result \rightarrow Passed

MOT #12 2019-12-17 14:44

MOT test number 761219426118

Result X Failed

Pass with rectification Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11 2018-12-21 13:22

MOT test number 797969906912

Advice Offside Rear Outer Brake lining(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Outer Brake lining(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



Fail

Fail

Result

WV56NUA

report date: 2024-03-28

✓ Passed

MOT #10 2018-12-20 14:02 231531071380 **MOT** test number Result × Failed **Advice** Offside Rear Outer Brake lining(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Nearside Rear Outer Brake lining(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a))

MOT #9

2017-10-21 13:44

MOT test number

494123213135

Result

✓ Passed

Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #8 2016-10-22 14:55

MOT test number 245107938164

Result ✓ Passed

MOT #7 2015-10-19 10:12

MOT test number 841432268730

Advice Rear seats not fitted at time of test

Nearside Front Position lamp not working (4.2.1 (a))

 MOT #6
 2014-10-30 16:50

 MOT test number
 799983404311

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #5

WV56NUA

report date: 2024-03-28

2013-10-23 12:06

MOT test number 487196493230

MOT #4 2012-10-26 09:30

MOT test number 409230302472

Result
✓ Passed

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2011-10-28 13:18

MOT test number 797761001345

Result
✓ Passed

MOT #2 2010-10-21 09:27

MOT test number 312394790473

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2009-10-22 09:12

MOT test number 793205699268

CarCheck.co.uk page 6/13





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



WV56NUA report date: 2024-03-28

Owner history

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		DTA

THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK CONTRACTOR	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



WV56NUA report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-30
Last registration	2024-03-07
Complete history	See info



Registration #1	2006-10-30	16 mi
Registration #2	2009-10-22	23.692 mi
Registration #3	2010-10-21	33.840 mi
Registration #4	2011-10-28	48.412 mi
Registration #5	2012-10-26	60.586 mi
Registration #6	2013-10-23	68.302 mi
Registration #7	2014-10-30	75.072 mi
Registration #8	2015-10-19	84.880 mi
Registration #9	2016-10-22	90.232 mi
Registration #10	2017-10-21	93.855 mi
Registration #11	2018-12-20	96.955 mi
Registration #12		71.777 44
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		77.777 46
Registration #21		73.777 es

More info >

CarCheck.co.uk page 12/13





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number 1ZZE525788