



HWI6A0U

report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SPORT
Colour	Blue
Year of manufacture	2016
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-01-29
Pictures	20
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2025-03-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #7 2024-03-23 10:06**MOT test number** 822148085541**Result** Passed**Next expiry date** 2025-03-26

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm outer edge (5.2.3 (e))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated split (5.3.4 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))

MOT #6 2023-03-27 15:04**MOT test number** 604640854821**Result** Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Windscreen wiper blade defective split (3.4 (b) (i))

MOT #5 2022-03-08 16:35**MOT test number** 859526078275**Result** Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2021-03-17 13:07**MOT test number** 205286425802**Result** ✓ Passed**MOT #3** 2020-02-06 11:27**MOT test number** 295265657140**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2020-02-06 11:27**MOT test number** 174543172653**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Headlamp cleaning device for LED or HID headlamp inoperative washer fluid filled up for mot (4.1.6 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-03-01 14:07**MOT test number** 614779948908**Result** ✓ Passed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-02
Last registration	2024-03-23
Complete history	See info



Registration #1	2016-03-02	7 mi
Registration #2	2019-03-01	20.669 mi
Registration #3	2020-02-06	28.595 mi
Registration #4	2020-02-06	28.595 mi
Registration #5	2020-02-06	28.595 mi
Registration #6	2020-02-06	28.595 mi
Registration #7	2020-02-06	28.595 mi
Registration #8	2020-02-06	28.595 mi
Registration #9	2020-02-06	28.595 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3890 mm
Wheel base	2430 mm
Kerb weight	1115 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M16A-1958544