



report date: 2024-03-28

General information

Make	FIAT
Model	500C LOUNGE
Colour	Red
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-09-23
Pictures	2
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	40
Total items failed	8

MOT #13	2023-09-21 09:53
MOT test number	881293014938
Result	✓ Passed
Next expiry date	2024-09-26

MOT #12	2022-09-23 10:05
MOT test number	327023627594
Result	✓ Passed

MOT #11	2022-09-21 12:54
MOT test number	917105929955
Result	✗ Failed
<div><div><b>DANGEROUS</b></div><div>Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))</div></div> <div><div><b>DANGEROUS</b></div><div>Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))</div></div> <div><div><b>MAJOR</b></div><div>Windscreen washer provides insufficient washer liquid (3.5 (a))</div></div>	

MOT #10	2021-09-27 14:28
MOT test number	283847901457
Result	✓ Passed

**MOT #9** 2018-12-01 09:49**MOT test number** 458636956255**Result** ✓ Passed**Advice** Tyre has a cut but not deep enough to reach the ply or cords All four (On the verge) (5.2.3 (d) (i))**Advice** Front Macpherson strut damaged but not seriously weakened Top mounts (5.3.3 (b) (i))**Advice** Tyre has a cut but not deep enough to reach the ply or cords All four (5.2.3 (d) (i))**Advice** Tyre worn close to legal limit/worn on edge All four (5.2.3 (e))**Advice** Front Shock absorbers light misting of oil or has limited damping effect Both (5.3.2 (b))**MOT #8** 2018-11-30 16:06**MOT test number** 525069854824**Result** ✗ Failed**Advice** Tyre has a cut but not deep enough to reach the ply or cords All four (On the verge) (5.2.3 (d) (i))**Advice** Front Macpherson strut damaged but not seriously weakened Top mounts (5.3.3 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge All four (5.2.3 (e))**Advice** Tyre has a cut but not deep enough to reach the ply or cords All four (5.2.3 (d) (i))**Advice** Front Shock absorbers light misting of oil or has limited damping effect Both (5.3.2 (b))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick Both (1.1.13 (a) (ii))

**MOT #7**

2017-11-15 17:06

**MOT test number**

672339395182

**Result**

✓ Passed

- Advice** Front Macpherson strut has slight movement at the upper attachment both (2.5.A.1c)
- Advice** Nearside Front deep cuts in tyre outer wall
- Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Rear deep cuts in tyre outer wall
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Boot can't open
- Advice** Offside Rear Tyre worn close to the legal limit deep cut (4.1.E.1)
- Advice** Offside Front deep cut in tyre walls
- Advice** Offside Lower Front suspension has slight movement at a wishbone pin or bush inner bush bonding deteriorated (2.5.A.1c)

**MOT #6**

2017-11-15 11:25

**MOT test number**

314195275137

**Result**

✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit deep cut (4.1.E.1)
- Advice** Nearside Front deep cuts in tyre outer wall
- Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Advice** Nearside Rear deep cuts in tyre outer wall
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Boot can't open
- Advice** Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front deep cut in tyre walls
- Advice** Offside Lower Front suspension has slight movement at a wishbone pin or bush inner bush bonding deteriorated (2.5.A.1c)

**MOT #5** 2016-09-13 16:50**MOT test number** 545995828810**Result** ✓ Passed**MOT #4** 2016-09-13 09:23**MOT test number** 702199084569**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Brake pipe inadequately supported BRAKET (3.6.B.1)**Advice** TRACKING REQUIRED**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened PITTED SCORED (3.5.1i)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Exhaust has a major leak of exhaust gases REAR BOX (7.1.2)**MOT #3** 2015-06-11 16:47**MOT test number** 268052965142**Result** ✓ Passed**Notice** Deep cut in o/s/r tyre outer wall**Notice** Cut in o/s/f tyre outer wall**Advice** Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)



MOT #2	2015-06-11 10:22
MOT test number	327872965106
Result	✗ Failed
Advice	Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Notice	Deep cut in o/s/r tyre outer wall
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Cut in o/s/f tyre outer wall
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1	2014-05-27 12:25
MOT test number	626887044133
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	26 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-






Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-26
Last registration	2023-09-21
Complete history	<a href="#">See info</a>



Registration #1	2011-07-26	23 mi
Registration #2	2014-05-27	23.267 mi
Registration #3	2015-06-11	29.711 mi
Registration #4	2015-06-11	29.711 mi
Registration #5	2016-09-13	37.245 mi
Registration #6	2016-09-13	37.245 mi
Registration #7	2017-11-15	44.793 mi
Registration #8	2017-11-15	44.793 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

**Engine number**

1647386