



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 T SE
Colour	Green
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	240 Nm at 1.850 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	35.8 mpg
Consumption combined	27.2 mpg
CO2 emission	237 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-07-07
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-28
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	18
Total items failed	6

MOT #20 2023-05-23 15:03

MOT test number 256097411717

Result ✓ Passed

Next expiry date 2024-05-28

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19 2022-05-25 16:31

MOT test number 431016296972

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #18 2021-05-19 11:36

MOT test number 312755634800

Result ✓ Passed

MOT #17 2021-05-19 11:36

MOT test number 990328639067

Result ✗ Failed

Pass with rectification Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))

**MOT #16** 2020-05-29 11:50**MOT test number** 719512149786**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Headlamp lens slightly defective Frosted (4.1.1 (b) (i))**MOT #15** 2019-05-28 08:48**MOT test number** 589174561257**Result** ✓ Passed**MOT #14** 2018-05-22 09:09**MOT test number** 307004541732**Result** ✓ Passed**MOT #13** 2017-05-22 09:13**MOT test number** 601375337755**Result** ✓ Passed**Advice** Rear Brake pads worn low.**Advice** Rear wiper blade split.**MOT #12** 2016-05-26 08:20**MOT test number** 730393847859**Result** ✓ Passed**Advice** Both front tyres perished and cracking on outer side walls.

**MOT #11** 2015-03-10 11:03**MOT test number** 717229065085**Result** ✓ Passed**Advice** Offside Outer Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-03-10 11:03**MOT test number** 817399065093**Result** ✗ Failed**Pass with rectification** Centre Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Outer Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2014-03-11 10:07**MOT test number** 177160474456**Result** ✓ Passed**Notice** Rear exhaust hangers in poor condition and one incomplete.**Notice** Water in N/S headlamp unit.**MOT #8** 2014-03-11 10:07**MOT test number** 448050074011**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear exhaust hangers in poor condition and one incomplete.**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Water in N/S headlamp unit.

**MOT #7** 2013-03-12 11:18**MOT test number** 937241173049**Result** ✓ Passed**Notice** Slight deterioration and small cuts to N/S/F tyre outer sidewall.**MOT #6** 2012-02-29 11:19**MOT test number** 738570962021**Result** ✓ Passed**MOT #5** 2011-03-04 12:01**MOT test number** 897613161062**Result** ✓ Passed**MOT #4** 2010-03-05 13:35**MOT test number** 482444560098**Result** ✓ Passed**MOT #3** 2009-03-06 12:18**MOT test number** 383665269033**Result** ✓ Passed**MOT #2** 2008-03-04 11:33**MOT test number** 544154068058**Result** ✓ Passed**MOT #1** 2008-03-04 11:33**MOT test number** 444154768034**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
28 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	28 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-05-29
Current registration	
Plate since	2019-05-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-18
Last registration	2023-05-23
Complete history	See info



Registration #1	2005-03-18	28 mi
Registration #2	2008-03-04	25.865 mi
Registration #3	2009-03-06	32.813 mi
Registration #4	2010-03-05	39.508 mi
Registration #5	2011-03-04	44.927 mi
Registration #6	2012-02-29	47.379 mi
Registration #7	2013-03-12	50.878 mi
Registration #8	2014-03-11	54.564 mi
Registration #9	2015-03-10	57.815 mi
Registration #10	2016-05-26	61.943 mi
Registration #11	2016-05-26	61.943 mi
Registration #12	2016-05-26	61.943 mi
Registration #13	2016-05-26	61.943 mi
Registration #14	2016-05-26	61.943 mi
Registration #15	2016-05-26	61.943 mi
Registration #16	2016-05-26	61.943 mi
Registration #17	2016-05-26	61.943 mi
Registration #18	2016-05-26	61.943 mi
Registration #19	2016-05-26	61.943 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	3677854