





General information

| Make | CITROEN |
|---------------------|--------------------------|
| Model | XSARA HDI VTR PLUS SCORE |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 138 mph |
| 0 - 60 mph | 12.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.8 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2022-03-08 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-03-31 |
|--------------------|------------|
| MOT pass rate | 92 % |
| MOT passed | 12 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #13 | | 2024-03-18 15:31 |
|-----------|--|------------------|
| MOT test | number | 806458026038 |
| Result | | Passed |
| Next expi | ry date | 2025-03-31 |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5. | 2.3 (d) (i)) |

| MOT #12 | | 2023-03-28 14:32 |
|----------|--|------------------|
| MOT test | number | 249465431493 |
| Result | | ✓ Passed |
| Advice | Rear Exhaust mounting defective (6.1.2 (a)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #11 | 2022-03-25 15:40 |
|---|--|
| MOT test number | 397736138175 |
| Result | ✓ Passed |
| Advice Rear Suspension component corroded but not s | seriously weakened beam axle (5.3.3 (b) (i)) |





| MOT #10 | 2021-03-08 09:17 |
|--|------------------|
| MOT test number | 935676329323 |
| Result | ✓ Passed |
| | |
| MOT #9 | 2020-03-18 14:38 |
| MOT test number | 671510309886 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2020-03-18 09:25 |
| MOT test number | 928478409649 |
| Result | 🗙 Failed |
| Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) | |

| MOT #7 | 2019-03-11 12:05 |
|-----------------|------------------|
| MOT test number | 585251292771 |
| Result | ✓ Passed |

| МОТ #6 | 2018-03-07 14:22 |
|-----------------|------------------|
| MOT test number | 268686770161 |
| Result | ✓ Passed |

| 2017-03-07 11:33 |
|------------------|
| 726070865681 |
| ✓ Passed |
| |

| MOT #4 | 2016-03-09 10:52 |
|-----------------|------------------|
| MOT test number | 440487624063 |
| Result | ✓ Passed |





| MOT #3 | 2015-03-12 11:40 |
|--|------------------|
| MOT test number | 386811475018 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2014-03-06 10:09 |
| MOT test number | 916945764045 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2013-03-19 09:17 |
| MOT test number | 249858973001 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |





Tax & MOT check

| ✓ Taxed | √ мот |
|--------------------------|---------------------------|
| Tax due: 1 March 2025 | Expires: 31 March 2025 |
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 31 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-03-31 |
| Last registration | 2024-03-18 |
| Complete history | See info |



| Registration #1 | 2010-03-31 | 25 mi |
|------------------|------------|------------|
| Registration #2 | 2013-03-19 | 19.251 mi |
| Registration #3 | 2014-03-06 | 24.779 mi |
| Registration #4 | 2015-03-12 | 29.658 mi |
| Registration #5 | 2016-03-09 | 34.931 mi |
| Registration #6 | 2017-03-07 | 40.359 mi |
| Registration #7 | 2018-03-07 | 46.762 mi |
| Registration #8 | 2019-03-11 | 53.070 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 est |
| Registration #14 | | 11.117 est |
| Registration #15 | | 11.777 mi |





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 81% |
| Children | 77% |
| Pedestrian | 32% |
| Safety systems | 83% |
| Overall rating | 71% |
| Video | see crash video |



| Dimensions & weight | |
|--|--------------------------|
| Width | 1853 mm |
| Height | 1456 mm |
| Length | 4779 mm |
| Wheel base | 2815 mm |
| Kerb weight | 1503 kg |
| Max. allowed weight | 2045 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 71 l |
| | 71 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 4 |