



AEI2LHN

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	Green
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-08
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #13	2023-07-21 10:32
MOT test number	359477194634
Result	✓ Passed
Next expiry date	2024-08-12

MOT #12	2022-08-05 09:33
MOT test number	359059899966
Result	✓ Passed

MOT #11	2021-08-13 13:40
MOT test number	332640199090
Result	✓ Passed

MOT #10	2021-01-13 16:10
MOT test number	791963507586
Result	✓ Passed
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #9** 2021-01-12 10:39**MOT test number** 574969353760**Result** ✗ Failed**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-01-17 09:07**MOT test number** 481901057757**Result** ✓ Passed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #7** 2020-01-17 09:07**MOT test number** 632680072983**Result** ✗ Failed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #6** 2019-01-18 11:32**MOT test number** 635737237940**Result** ✓ Passed

**MOT #5** 2018-05-17 15:18**MOT test number** 240380539684**Result** ✓ Passed**MOT #4** 2018-05-16 15:08**MOT test number** 295554477738**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2017-05-18 14:17**MOT test number** 308579933838**Result** ✓ Passed**Advice** Nearside Rear Wheel Buckled**Advice** Tyres Worn Unevenly**Advice** Alternator Belt Cracked**MOT #2** 2016-06-23 09:50**MOT test number** 119872519232**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Nail in tyre**Advice** Both rear tyres slight out of shape on inner edge



MOT #1	2015-07-17 10:24
MOT test number	177578295157
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-08-16
Last registration	2023-07-21
Complete history	See info



Registration #1	2012-08-16	9 mi
Registration #2	2015-07-17	14.273 mi
Registration #3	2016-06-23	25.314 mi
Registration #4	2017-05-18	36.519 mi
Registration #5	2018-05-16	48.596 mi
Registration #6	2018-05-17	48.661 mi
Registration #7	2019-01-18	56.333 mi
Registration #8	2020-01-17	68.604 mi
Registration #9	2020-05-20	75.377 mi
Registration #10	2020-05-20	75.377 mi
Registration #11	2020-05-20	75.377 mi
Registration #12	2020-05-20	75.377 mi
Registration #13	2020-05-20	75.377 mi
Registration #14	2020-05-20	75.377 mi
Registration #15	2020-05-20	75.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1405 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

A923J257