





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG
Colour	Silver
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-07-04

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-09
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #11	2023-07-06 10:29
MOT test number	666887026740
Result	✓ Passed
Next expiry date	2024-07-09

MOT #10		2022-06-30 14:17
MOT test	number	214933763709
Result		✓ Passed
Advice (e))	Front Tyre worn close to legal limit/worn on edge offside + near	side wearing on inside edge (5.2.3
Advice	Nearside Rear Nail in tyre	

CarCheck.co.uk page 3/12



GL14DXY

report date: 2024-03-28

MOT #9 2022-06-30 08:51 **MOT** test number 208812417597 Result × Failed **MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) Advice Nearside Rear Nail in tyre Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) **MAJOR** Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a)) Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **MAJOR Advice** Front Tyre worn close to legal limit/worn on edge offside + nearside wearing on inside edge (5.2.3 (e)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #8

MOT test number

Result

Advice General Underbody Corrosion

 MOT #7
 2021-04-23 08:47

 MOT test number
 266562939299

 Result
 ✓ Passed

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



Result

GL14DXY report date: 2024-03-28

Passed

MOT test number

Fasult

Mor test number

Salo44980976

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #4
 2019-04-27 08:20

 MOT test number
 465380671677

 Result
 ✓ Passed

 MOT #3
 2019-04-27 08:20

 MOT test number
 826558527370

 Result
 X Failed

 Pass with rectification
 Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #2
 2018-07-21 07:55

 MOT test number
 936010885107

 Result
 ✓ Passed

 MOT #1
 2017-05-01 10:10

 MOT test number
 557547977967

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-01
Last registration	2023-07-06
Complete history	See info



Registration #1	2014-05-01	14 mi
Registration #2	2017-05-01	54.511 mi
Registration #3	2018-07-21	65.653 mi
Registration #4	2019-04-27	72.848 mi
Registration #5	2019-04-27	72.848 mi
Registration #6	2020-04-13	79.825 mi
Registration #7	2020-04-13	79.825 mi
Registration #8		71.777 es
Registration #9		11.177 es
Registration #10		71.777 es
Registration #11		11.117 es
Registration #12		11.177 es
Registration #13		71.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1564 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
CarChack so uk	nago 12/1:

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CFFBJ33731