



PEUGEOT



OU67MWC

report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER BLUE HDI S L1
Colour	White
Year of manufacture	2017
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-24
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #6	2023-07-17 11:25
MOT test number	338479682176
Result	✓ Passed
Next expiry date	2024-07-18
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside sill dented
Advice	Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #5	2023-07-14 12:19
MOT test number	495743927635
Result	✗ Failed
Advice	Offside sill dented
Advice	Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Parking brake inoperative on one side cable snapped (1.4.1 (a))

**MOT #4** 2022-07-15 12:00**MOT test number** 119139779450**Result** ✓ Passed**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside sill dented**MOT #3** 2022-07-15 08:28**MOT test number** 484731212561**Result** ✗ Failed**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Minor** Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Dipswitch operation does not extinguish all main beam headlamps leaving at least one pair of dipped beam headlamps alternates main beam from nearside to offside (4.1.3 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside sill dented**MOT #2** 2021-07-19 10:03**MOT test number** 752628353995**Result** ✓ Passed**MOT #1** 2020-09-22 11:59**MOT test number** 345758019187**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
18 July 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		18 July 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	OU67MWC
Plate since	2024-03-29
Current registration	OU67MWC
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-30
Last registration	2023-07-17
Complete history	See info



Registration #1	2017-09-30	27 mi
Registration #2	2020-09-22	102.191 mi
Registration #3	2021-07-19	107.209 mi
Registration #4	2022-05-20	111.217 mi
Registration #5	2022-05-20	111.217 mi
Registration #6	2022-05-20	111.217 mi
Registration #7	2022-05-20	111.217 mi
Registration #8	2023-07-17	111.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1292 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBHB0040320